# WAYNE STATE UNIVERSITY OLD MAIN BUILDING - ENCLOSURE REPAIRS WSU PROJECT # 001-400580







SITE LOCATION







POINT AT 2nd AVENUE

DUMPSTER / -STAGING AREA. COORDINATE WITH WSU PROJECT MANAGER ON TRAFFIC AND FINAL LOCATION



SITE PLAN NOT TO SCALE

HANCOCK ST.

1. Drawings and specifications are intended to be a schematic representation of the existing conditions and overall design intent. Contractor is responsible to review existing conditions and develop the specific scope of work for the project, which shall meet the design intent as well as be in accordance with all applicable building codes.

2. Contractor shall submit a developed and complete scope of work document, including project specific shop drawings and product data sheets.

3. Permits: Contractor shall secure any required permits prior to proceeding with any work and shall coordinate building inspections with the Owner, including the WSU Fire Inspector. General Note:

Drawing provided are approximate scale based on original design drawings. Contractor to verify all dimensions.

BARRICADE ENTRANCE LOCATION AT WARREN AVE DURING WORK	INITIALS/DATE         DRAWN INT       11/1/2024         APPROVED       11/1/2024         REVISED 1       50% CHECK SET         APPROVED       1/24/2025         REVISED 2       1         APPROVED       1/24/2025         REVISED 3       1         APPROVED       1         SUED FOR BID       2/20/2025
DUMPSTER / STAGING AREA. COORDINATE WITH WSU PROJECT MANAGER ON TRAFFIC AND FINAL LOCATION	WAYNE STATE UNIVERSITY OLD MAIN BUILDING WSU PROJECT #001-400580 SITE PLAN
	Building Science Solutions Building and Construction eet - Plymouth - Michigan - 481 70 - Tel 248.957,9911



S

SP-1



General: The following notes are intended to illustrate general locations of typical work items included in the base bid, and are not intended to be a complete scope of work. Refer to the project specifications for complete description of all work to be performed. For simplification, work items pertaining to the "original building" are noted as "OB", while work pertaining to the newer addition are noted as "NA".

(1.) NA: Remove and replace thru-wall flashing at the stone tower with new. Refer to Detail D7/A501. [Approx. 15 LF]

- $\overline{(2.)}$  NA: Remove and replace thru-wall flashing along penthouse with new. Refert to Detail D9/A501. [Approx. 70 LF]
- **3. OB:** Perform metal roof repairs, which includes providing new flashing at the aluminum cladded battens with proper detailing at transition points, providing new fasteners, with washers, to aluminum cladded battens, providing a watertight barrier at the transition from the existing BUR to metal sloped roof, and sealing exposed joints in the metal panels. Refer to Detail D25/A504.
- **4. OB:** Re-secure existing snowguards (all elevations). [Approx. 315 LF]. Refer to Detail D29/A504.
- **5. NA:** Remove and replace existing window thru-wall flashing with new. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Details D13/A502 & D14/502. [Approx. 180 LF]
- $\langle 6. \rangle$  NA: Remove and replace existing shelf angles. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Detail D8/A501. [Approx. 230 LF]
- (7.) NA: Remove and replace control joints with new. Refer to Details D3/A500 & D12/A502. [Approx. 2,150 LF]
- $(\hat{\mathbf{8}})$  **NA:** Remove and replace window perimeter sealants with new. Refer to Details D3/A500 & D12/A502. [Approx. 1,380 LF]
- (9.) NA: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Details D1/A500 & D2/A500. [Approx. 500 SF]
- $(\mathbf{10})$  NA: Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 16 units].
- (11) **OB:** Remove and replace window perimeter sealants. Refer to Details D3/A500 & D12/A502. [Approx. 18,120 LF]
- (12) OB: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Detail D1/A500 [Approx. 16,410 SF general & 1,014 SF severe deterioration]. Provide a unit price for localized and isolated repairs.
- $\langle \mathbf{13} \rangle$  **OB:** Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 251 units]. Provide a unit price for localized and isolated repairs.
- (14) OB: Rout and seal cracks in the brick and stone walls. Refer to Details D7/A501, D8/A501 & D9/501. [Approx. 185 LF]. Provide a unit price for localized and isolated repairs.
- (15) OB: Repair damaged and/or spalled stone in the limestone bands using Dutchman style repairs. Refer to Details D21/A503, D22/A503 & D23/A503. [Approx. 54 SF]. Provide a unit price for localized and isolated repairs.
- (16) OB: Repair damaged and/or spalled terracotta stone. Refer to Detail D18/A503. [Approx. 122 SF]. Provide a unit price for localized and isolated repairs.
- (17) OB: Rout and seal cracks in the terracotta stone. Refer to Detail D19/A503. [Approx. 48 LF]. Provide a unit price for localized and isolated repairs.
- $\langle \mathbf{18} \rangle$  **OB:** If heavy rust pack and section loss is visible in the window lintel, remove and replace existing lintels with new and associated flashing above windows. If surface corrosion with no section loss is visible, clean and paint existing lintels. Refer to Details D10/A501 & D11/A501. [Approx. 953 LF]
- (19) OB: If heavy rust pack and section loss is visible in the shelf angles, remove and replace existing shelf angles with new and associated flashing. If surface corrosion with no section loss is visible, clean and paint existing shelf angles. Similar to Detail D8/A501. [Approx. 186 LF]
- $\langle 20 \rangle$  OB: Repairs to the courtyard terrace concrete steps. Refer to Detail D17/A502. Allow for lump sum of \$10,000.
- (21) OB: Repairs to the spalled concrete retaining wall on the west elevation of the original building. Refer to Detail D21/503. Allow for lump sum of \$10,000.
- $\langle 22 \rangle$  OB: Repairs to the damaged keystone arch at the west elevation entrance. Refer to Detail D24/A504. Allow for lump sum of \$20,000.
- (23) **OB:** Re-securement and/or replacement of the copper flashing. Refer to Detail D23/A503. [Approx. 15 LF]. Allow for lump sum of \$15,000.

INITIALS/DATE DRAWN INT 11/1/2024 APPROVED 11/1/2024 REVISED 1 50% CHECK SET APPROVED 1/24/2025 REVISED 2 APPROVED REVISED 3 APPROVED APPROVED FOR BIDS ISSUED FOR BID 2/20/2025

580 SITY SITY NNN  $\overline{\Box}$ STATE **ADDITION** В MAIN WAYNE NSN old NEW g Science Solutions g and Construction • Michigan • 481 70 • Tel 248 957, 991 Building Suilding S

RP-1



General: The following notes are intended to illustrate general locations of typical work items included in the base bid, and are not intended to be a complete scope of work. Refer to the project specifications for complete description of all work to be performed. For simplification, work items pertaining to the "original building" are noted as "OB", while work pertaining to the newer addition are noted as "NA".

- $\langle \mathbf{\hat{1}} \rangle$  **NA:** Remove and replace thru-wall flashing at the stone tower with new. Refer to Detail D7/A501. [Approx. 15 LF]
- (2.) NA: Remove and replace thru-wall flashing along penthouse with new. Refert to Detail D9/A501. [Approx. 70 LF]

3 LOCATION OF WORK INDICATED BY HATCHED

AREA

- **3. OB:** Perform metal roof repairs, which includes providing new flashing at the aluminum cladded battens with proper detailing at transition points, providing new fasteners, with washers, to aluminum cladded battens, providing a watertight barrier at the transition from the existing BUR to metal sloped roof, and sealing exposed joints in the metal panels. Refer to Detail D25/A504.
- $\overline{(4.)}$  **OB:** Re-secure existing snowguards (all elevations). [Approx. 315 LF]. Refer to Detail D29/A504.
- $\overline{(5.)}$  NA: Remove and replace existing window thru-wall flashing with new. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Details D13/A502 & D14/502. [Approx. 180 LF]
- **6. NA:** Remove and replace existing shelf angles. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Detail D8/A501. [Approx. 230 LF]
- (7.) NA: Remove and replace control joints with new. Refer to Details D3/A500 & D12/A502. [Approx. 2,150 LF]
- (8.) NA: Remove and replace window perimeter sealants with new. Refer to Details D3/A500 & D12/A502. [Approx. 1,380 LF]
- $\langle 9. \rangle$  NA: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Details D1/A500 & D2/A500. [Approx. 500 SF]
- $\langle 10 \rangle$  NA: Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 16 units].
- $\langle 11 \rangle$  **OB:** Remove and replace window perimeter sealants. Refer to Details D3/A500 & D12/A502. [Approx. 18,120 LF]
- (12) OB: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Detail D1/A500 [Approx. 16,410 SF general & 1,014 SF severe deterioration]. Provide a unit price for localized and isolated repairs.
- $\langle 13 \rangle$  OB: Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 251 units]. Provide a unit price for localized and isolated repairs.
- (14) OB: Rout and seal cracks in the brick and stone walls. Refer to Details D7/A501, D8/A501 & D9/501. [Approx. 185 LF]. Provide a unit price for localized and isolated repairs.
- (15) OB: Repair damaged and/or spalled stone in the limestone bands using Dutchman style repairs. Refer to Details D21/A503, D22/A503 & D23/A503. [Approx. 54 SF]. Provide a unit price for localized and isolated repairs.
- (16) OB: Repair damaged and/or spalled terracotta stone. Refer to Detail D18/A503. [Approx. 122 SF]. Provide a unit price for localized and isolated repairs.
- (17) OB: Rout and seal cracks in the terracotta stone. Refer to Detail D19/A503. [Approx. 48 LF]. Provide a unit price for localized and isolated repairs.
- $\langle \mathbf{18} \rangle$  **OB:** If heavy rust pack and section loss is visible in the window lintel, remove and replace existing lintels with new and associated flashing above windows. If surface corrosion with no section loss is visible, clean and paint existing lintels. Refer to Details D10/A501 & D11/A501. [Approx. 953 LF]
- (19) OB: If heavy rust pack and section loss is visible in the shelf angles, remove and replace existing shelf angles with new and associated flashing. If surface corrosion with no section loss is visible, clean and paint existing shelf angles. Similar to Detail D8/A501. [Approx. 186 LF]
- $\langle 20 \rangle$  OB: Repairs to the courtyard terrace concrete steps. Refer to Detail D17/A502. Allow for lump sum of \$10,000.
- $\langle 21 \rangle$  OB: Repairs to the spalled concrete retaining wall on the west elevation of the original building. Refer to Detail D21/503. Allow for lump sum of \$10,000.
- (22) OB: Repairs to the damaged keystone arch at the west elevation entrance. Refer to Detail D24/A504. Allow for lump sum of \$20,000.
- (23) OB: Re-securement and/or replacement of the copper flashing. Refer to Detail D23/A503. [Approx. 15 LF]. Allow for lump sum of \$15,000.

APPROVED 1 1/1/2024 REVISED 1 50% CHECK SE APPROVED 2 1/24/2025 REVISED 3 APPROVED 6 JUS APPROVED FOR BID 2/20/2025
REVISED 1 50% CHECK SE APPROVED 1/24/2025 REVISED 2 APPROVED 3 APPROVED 60 BIDS ISSUED FOR BID 2/20/2025 NURNING 100 100 100 100 100 100 100 100 100 10
APPROVED 1/24/2025 REVISED 2 APPROVED 3 APPROVED APPROVED FOR BIDS ISSUED FOR BID 2/20/2025 NIGNIN HUBION NULL APPROVED APPROVED APPROVED FOR BID 2/20/2025
REVISED 2 APPROVED APPROVED FOR BIDS ISSUED FOR BID NUCLAN NORO HOUS NUCLAN NORO HOUS NUCLAN NORO HOUS NUCLAN NORO HOUS NUCLAN NORO HOUS NUCLAN NORO HOUS NUCLAN NUCL
APPROVED 3 APPROVED TOR BIDS ISSUED FOR BID 2/20/2025 NUCI HON BID 100 100 100 100 100 100 100 100 100 10
REVISED 3 APPROVED APPROVED FOR BIDS ISSUED FOR BID 2/20/2025 NC HON BID 010 WAIN BUICH NO 1000 0100 WAIN BUICH NO 1000 0100 WAIN BUICH NO 1000 WAIN BUICH NO 10000 WAIN BUICH NO 1000 WAIN B
APPROVED FOR BIDS ISSUED FOR BID OID MAINE RATE UNICEUSITY ORD PORTURATION NON PROJECT #001-00280 NAN BUIDING NON PLOOE LAN AUTOMOTION NON PLOUE L
APPROVED FOR BIDS ISSUED FOR BID ORD MAINE STATE UNIVERSITY ORD MAINE BULLONG NOL HOOLE OL MAINE BULLONG NOL HOULE BULLONG NOL HO
NAVIE STATE UNVERSITY NAVIE STATE UNVERSITY OLD MAIN BUILDING WSU PROJECT #001-400580 WSU PROJECT #001-400580 ORIGINAL BUILDING - ROOF PLAN
WAYNE STATE UNVERSITY OLD MAIN BUILDING WSU PROJECT #001-400580 ORIGINAL BUILDING - ROOF PLAN

INITIALS/DATE



RP-2

Drawing provided are approximate scale based on original design drawings. Contractor





A = 100

## EAST ELEVATION

SCALE: N.T.S.

## SYMBOL LEGEND

ADDITIONAL SYMBOLS MAY BE SHOWN ON THE DRAWING FOR SPECIFIC PROJECTS.

▲ #	DAMAGED BRICK (# = NO. OF BRICKS)		DAMAGED/MISSING LIMESTONE		SPALLED/DAMAGED TERRACOTTA		CONTROL JOINT
	DAMAGED SHELF ANGLE/LINTEL	ξL	CRACKED LIMESTONE	ξT	CRACKED TERRACOTTA		
NOT	NOTE: THE SYMBOLS SHOWN ARE USED ON OUR DRAWINGS TO INDICATE ROOF FEATURES.						

### GENERAL NOTES:

- 1. Drawings and specifications are intended to be a schematic representation of the existing conditions and overall design intent. Contractor is responsible to review existing conditions and develop the specific scope of work for the project, which shall meet the design intent as well as be in accordance with all applicable building codes.
- 2. Contractor shall submit a developed and complete scope of work document, including project specific shop drawings and product data sheets.
- 3. Permits: Contractor shall secure any required permits prior to proceeding with any work and shall coordinate building inspections with the Owner, including the WSU Fire Inspector.

General Note: Drawing provided are approximate scale based on original design drawings. Contractor to verify all dimensions.

General: The following notes are intended to illustrate general locations of typical work items included in the base bid, and are not intended to be a complete scope of work. Refer to the project specifications for complete description of all work to be performed. For simplification, work items pertaining to the "original building" are noted as "OB", while work pertaining to the newer addition are noted as "NA".

- (1.) NA: Remove and replace thru-wall flashing at the stone tower with new. Refer to Detail D7/A501. [Approx. 15 LF]
- (2.) NA: Remove and replace thru-wall flashing along penthouse with new. Refert to Detail D9/A501. [Approx. 70 LF]
- $\overline{(3.)}$  **OB:** Perform metal roof repairs, which includes providing new flashing at the aluminum cladded battens with proper detailing at transition points, providing new fasteners, with washers, to aluminum cladded battens, providing a watertight barrier at the transition from the existing BUR to metal sloped roof, and sealing exposed joints in the metal panels. Refer to Detail D25/A504.
- **4. OB:** Re-secure existing snowguards (all elevations). [Approx. 315 LF]. Refer to Detail D29/A504.
- **5. NA:** Remove and replace existing window thru-wall flashing with new. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Details D13/A502 & D14/502. [Approx. 180 LF]
- $\langle 6. \rangle$  NA: Remove and replace existing shelf angles. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Detail D8/A501. [Approx. 230 LF]
- (7.) NA: Remove and replace control joints with new. Refer to Details D3/A500 & D12/A502. [Approx. 2,150 LF]
- (8.) NA: Remove and replace window perimeter sealants with new. Refer to Details D3/A500 & D12/A502. [Approx. 1,380 LF]
- (9.) NA: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Details D1/A500 & D2/A500. [Approx. 500 SF]
- (10) NA: Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 16 units].
- (11) **OB:** Remove and replace window perimeter sealants. Refer to Details D3/A500 & D12/A502. [Approx. 18,120 LF]
- (12) OB: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Detail D1/A500 [Approx. 16,410 SF general & 1,014 SF severe deterioration]. Provide a unit price for localized and isolated repairs.
- (13) OB: Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 251 units]. Provide a unit price for localized and isolated repairs.
- (14) OB: Rout and seal cracks in the brick and stone walls. Refer to Details D7/A501, D8/A501 & D9/501. [Approx. 185 LF]. Provide a unit price for localized and isolated repairs.
- (15) OB: Repair damaged and/or spalled stone in the limestone bands using Dutchman style repairs. Refer to Details D21/A503, D22/A503 & D23/A503. [Approx. 54 SF]. Provide a unit price for localized and isolated repairs.
- (16) OB: Repair damaged and/or spalled terracotta stone. Refer to Detail D18/A503. [Approx. 122 SF]. Provide a unit price for localized and isolated repairs.
- (17) **OB:** Rout and seal cracks in the terracotta stone. Refer to Detail D19/A503. [Approx. 48 LF]. Provide a unit price for localized and isolated repairs.
- (18) OB: If heavy rust pack and section loss is visible in the window lintel, remove and replace existing lintels with new and associated flashing above windows. If surface corrosion with no section loss is visible, clean and paint existing lintels. Refer to Details D10/A501 & D11/A501. [Approx. 953 LF]
- (19) OB: If heavy rust pack and section loss is visible in the shelf angles, remove and replace existing shelf angles with new and associated flashing. If surface corrosion with no section loss is visible, clean and paint existing shelf angles. Similar to Detail D8/A501. [Approx. 186 LF]
- $\langle 20 \rangle$  OB: Repairs to the courtyard terrace concrete steps. Refer to Detail D17/A502. Allow for lump sum of \$10,000.
- (21) OB: Repairs to the spalled concrete retaining wall on the west elevation of the original building. Refer to Detail D21/503. Allow for lump sum of \$10,000.
- (22) **OB:** Repairs to the damaged keystone arch at the west elevation entrance. Refer to Detail D24/A504. Allow for lump sum of \$20,000.
- (23) **OB:** Re-securement and/or replacement of the copper flashing. Refer to Detail D23/A503. [Approx. 15 LF]. Allow for lump sum of \$15,000.

INITIALS/DATE         DRAWN INT         11/1/2024         APPROVED         11/1/2024         REVISED 1         50% CHECK SET         APPROVED						
REVISED 2       APPROVED       REVISED 3       APPROVED       APPROVED FOR BIDS       ISSUED FOR BID       2/20/2025						
WAYNE STATE UNIVERSITY	old Main Building - New Addition	WSU PROJECT #001-400580	EAST ELEVATION			
Building Science Solutions Building and Construction 200-4500 Helm Street - Plymouth - Michigan - 481 70 - Tel 248 957.9911						

A-100

		20'-0"	
OURTH FLOOR EL.:	157'-	.7"	-
		12'-5"	
HIRD FLOOR EL.:	145	-2"	NEA
ECOND FLOOR EL.:	131'-	2-21	
араналаланара жаланалан каналара на жалара каналаран каналаран каналаран каналаран каналаран каналаран канарал	ar elakungananan essan e		hau
		17° 7 <sup>11</sup>	
RST FLOOR EL.:	9944° a	- O <sup>w</sup>	1004
		14*-0"	
SMT FLOOR FL	100'-	-0"	

177'-7"



B	$\bigotimes$	SEVERE BRICK REPOINTING	<b>A</b> #	DAMAGED BRICK (# = NO. OF BRICKS)		DAMAGED/MISSING LIMESTONE		SPALLED/DAMAGED TERRACOTTA		CONTROL JOINT
	5	CRACKED BRICK/STONE		DAMAGED SHELF ANGLE/LINTEL	L	CRACKED LIMESTONE	Т	CRACKED TERRACOTTA		

General: The following notes are intended to illustrate general locations of typical work items included in the base bid, and are not intended to be a complete scope of work. Refer to the project specifications for complete description of all work to be performed. For simplification, work items pertaining to the "original building" are noted as "OB", while work pertaining to the newer addition are noted as "NA".

- **NA:** Remove and replace thru-wall flashing at the stone tower with new. Refer to Detail D7/A501. [Approx. 15 LF]
- (2.) NA: Remove and replace thru-wall flashing along penthouse with new. Refert to Detail D9/A501. [Approx. 70 LF]
- $\langle 3. \rangle$ **OB:** Perform metal roof repairs, which includes providing new flashing at the aluminum cladded battens with proper detailing at transition points, providing new fasteners, with washers, to aluminum cladded battens, providing a watertight barrier at the transition from the existing BUR to metal sloped roof, and sealing exposed joints in the metal panels. Refer to Detail D25/A504.
- (4.) **OB:** Re-secure existing snowguards (all elevations). [Approx. 315 LF]. Refer to Detail D29/A504.
- **(5.)** NA: Remove and replace existing window thru-wall flashing with new. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Details D13/A502 & D14/502. [Approx. 180 LF]
- **6. NA:** Remove and replace existing shelf angles. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Detail D8/A501. [Approx. 230 LF]
- (7.) **NA:** Remove and replace control joints with new. Refer to Details D3/A500 & D12/A502. [Approx. 2,150 LF]
- $\langle 8. \rangle$  NA: Remove and replace window perimeter sealants with new. Refer to Details D3/A500 & D12/A502. [Approx. 1,380 LF]
- (9.) NA: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Details D1/A500 & D2/A500. [Approx. 500 SF]
- (10) NA: Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 16 units].
- (11) OB: Remove and replace window perimeter sealants. Refer to Details D3/A500 & D12/A502. [Approx. 18,120 LF]
- (12) OB: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Detail D1/A500 [Approx. 16,410 SF general & 1,014 SF severe deterioration]. Provide a unit price for localized and isolated repairs.
- $\langle 13 \rangle$  **OB:** Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 251 units]. Provide a unit price for localized and isolated repairs.
- (14) OB: Rout and seal cracks in the brick and stone walls. Refer to Details D7/A501, D8/A501 & D9/501. [Approx. 185 LF]. Provide a unit price for localized and isolated repairs.
- (15) OB: Repair damaged and/or spalled stone in the limestone bands using Dutchman style repairs. Refer to Details D21/A503, D22/A503 & D23/A503. [Approx. 54 SF]. Provide a unit price for localized and isolated repairs.
- (16) OB: Repair damaged and/or spalled terracotta stone. Refer to Detail D18/A503. [Approx. 122 SF]. Provide a unit price for localized and isolated repairs.
- (17) **OB:** Rout and seal cracks in the terracotta stone. Refer to Detail D19/A503. [Approx. 48 LF]. Provide a unit price for localized and isolated repairs.
- (18) OB: If heavy rust pack and section loss is visible in the window lintel, remove and replace existing lintels with new and associated flashing above windows. If surface corrosion with no section loss is visible, clean and paint existing lintels. Refer to Details D10/A501 & D11/A501. [Approx. 953 LF]
- (19) OB: If heavy rust pack and section loss is visible in the shelf angles, remove and replace existing shelf angles with new and associated flashing. If surface corrosion with no section loss is visible, clean and paint existing shelf angles. Similar to Detail D8/A501. [Approx. 186 LF]
- (20) OB: Repairs to the courtyard terrace concrete steps. Refer to Detail D17/A502. Allow for lump sum of \$10,000.
- (21) OB: Repairs to the spalled concrete retaining wall on the west elevation of the original building. Refer to Detail D21/503. Allow for lump sum of \$10,000.
- (22) OB: Repairs to the damaged keystone arch at the west elevation entrance. Refer to Detail D24/A504. Allow for lump sum of \$20,000.
- (23) **OB:** Re-securement and/or replacement of the copper flashing. Refer to Detail D23/A503. [Approx. 15 LF]. Allow for lump sum of \$15,000.

INITIALS/DATE DRAWN INT 11/1/2024 APPROVED 11/1/2024 REVISED 1 50% CHECK SET 1/24/2025 APPROVED REVISED 2 APPROVED REVISED 3 APPROVED APPROVED FOR BIDS ISSUED FOR BID 2/20/2025 ADDITION -400580 RUL NEV 001 ININ (7 ELEVATION ATE ST Z Ω Ш  $\geq$ NSN WEST

> SC III J Science Solutions J and Constructior Michigan - 481 70 - Tel 248 957,991 Building Building meet - Plymouth - A S

WAYN

 $\Box$ 

Ъ







<b>A</b> #	DAMAGED BRICK (# = NO. OF BRICKS)		DAMAGED/MISSING LIMESTONE		SPALLED/DAMAGED TERRACOTTA	— —	CONTROL JOINT		
	DAMAGED SHELF ANGLE/LINTEL	ξL	CRACKED LIMESTONE	ξT	CRACKED TERRACOTTA				

**NOTE:** THE SYMBOLS SHOWN ARE USED ON OUR DRAWINGS TO INDICATE ROOF FEATURES. ADDITIONAL SYMBOLS MAY BE SHOWN ON THE DRAWING FOR SPECIFIC PROJECTS.



- (1.) **NA:** Remove and replace thru-wall flashing at the stone tower with new. Refer to Detail D7/A501. [Approx. 15 LF]
- (2.) NA: Remove and replace thru-wall flashing along penthouse with new. Refert to Detail D9/A501. [Approx. 70 LF]
- (3.) **OB:** Perform metal roof repairs, which includes providing new flashing at the aluminum cladded battens with proper detailing at transition points, providing new fasteners, with washers, to aluminum cladded battens, providing a watertight barrier at the transition from the existing BUR to metal sloped roof, and sealing exposed joints in the metal panels. Refer to Detail D25/A504.
- (4.) **OB:** Re-secure existing snowguards (all elevations). [Approx. 315 LF]. Refer to Detail D29/A504.
- **5. NA:** Remove and replace existing window thru-wall flashing with new. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Details D13/A502 & D14/502. [Approx. 180 LF]
- 6. **NA:** Remove and replace existing shelf angles. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Detail D8/A501. [Approx. 230 LF]
- (7.) NA: Remove and replace control joints with new. Refer to Details D3/A500 & D12/A502. [Approx. 2,150 LF]
- (8.) NA: Remove and replace window perimeter sealants with new. Refer to Details D3/A500 & D12/A502. [Approx. 1,380 LF]
- $\overline{(9.)}$  NA: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Details D1/A500 & D2/A500. [Approx. 500 SF]
- (10) NA: Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 16 units].
- (11) OB: Remove and replace window perimeter sealants. Refer to Details D3/A500 & D12/A502. [Approx. 18,120 LF]
- (12) OB: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Detail D1/A500 [Approx. 16,410 SF general & 1,014 SF severe deterioration]. Provide a unit price for localized and isolated repairs.
- (13) **OB:** Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 251 units]. Provide a unit price for localized and isolated repairs.
- (14) **OB:** Rout and seal cracks in the brick and stone walls. Refer to Details D7/A501, D8/A501 & D9/501. [Approx. 185 LF]. Provide a unit price for localized and isolated repairs.
- (15) OB: Repair damaged and/or spalled stone in the limestone bands using Dutchman style repairs. Refer to Details D21/A503, D22/A503 & D23/A503. [Approx. 54 SF]. Provide a unit price for localized and isolated repairs.
- (16) OB: Repair damaged and/or spalled terracotta stone. Refer to Detail D18/A503. [Approx. 122 SF]. Provide a unit price for localized and isolated repairs.
- (17) OB: Rout and seal cracks in the terracotta stone. Refer to Detail D19/A503. [Approx. 48 LF]. Provide a unit price for localized and isolated repairs.
- (18) OB: If heavy rust pack and section loss is visible in the window lintel, remove and replace existing lintels with new and associated flashing above windows. If surface corrosion with no section loss is visible, clean and paint existing lintels. Refer to Details D10/A501 & D11/A501. [Approx. 953 LF]
- (19) OB: If heavy rust pack and section loss is visible in the shelf angles, remove and replace existing shelf angles with new and associated flashing. If surface corrosion with no section loss is visible, clean and paint existing shelf angles. Similar to Detail D8/A501. [Approx. 186 LF]
- (20) OB: Repairs to the courtyard terrace concrete steps. Refer to Detail D17/A502. Allow for lump sum of \$10,000.
- (21) **OB:** Repairs to the spalled concrete retaining wall on the west elevation of the original building. Refer to Detail D21/503. Allow for lump sum of \$10,000.
- (22) OB: Repairs to the damaged keystone arch at the west elevation entrance. Refer to Detail D24/A504. Allow for lump sum of \$20,000.
- (23) **OB:** Re-securement and/or replacement of the copper flashing. Refer to Detail D23/A503. [Approx. 15 LF]. Allow for lump sum of \$15,000.

	I	NITIALS/DATE
RAWN	INT	11/1/2024
PPROVE	D	11/1/2024
REVISED	1	50% CHECK SET
PPROVE	D	1/24/2025
REVISED	2	
PPROVE	D	
REVISED	3	
PPROVE	D	
PPROVED	FOR	BIDS
SSUED FOR I	BID	2/20/2025







A-102

based on original design drawings. Contractor

114'-0"

177'-7"

157'--7"

145'-2"

131'-7"

100'-0"

representation of the existing conditions and overall design intent. Contractor is responsible to review existing conditions and develop the specific scope of work for the project, which shall meet the design intent as well as be in accordance with all

2. Contractor shall submit a developed and complete scope of work document, including project specific shop drawings and

3. Permits: Contractor shall secure any required permits prior to proceeding with any work and shall coordinate building inspections with the Owner, including the WSU Fire Inspector.





## SOUTH ELEVATION

SCALE: N.T.S.

SYMBOL LEGEND

-						
DAMAGED BRICK (# = NO. OF BRICKS)		DAMAGED/MISSING LIMESTONE		SPALLED/DAMAGED TERRACOTTA		CONTROL JOINT
DAMAGED SHELF ANGLE/LINTEL	λ ζ L	CRACKED LIMESTONE	ξT	CRACKED TERRACOTTA		

NOTE: THE SYMBOLS SHOWN ARE USED ON OUR DRAWINGS TO INDICATE ROOF FEATURES. ADDITIONAL SYMBOLS MAY BE SHOWN ON THE DRAWING FOR SPECIFIC PROJECTS.

GENERAL NOTES:

- 1. Drawings and specifications are intended to be a schematic representation of the existing conditions and overall design intent. Contractor is responsible to review existing conditions and develop the specific scope of work for the project, which
- shall meet the design intent as well as be in accordance with all applicable building codes. 2. Contractor shall submit a developed and complete scope of work document, including project specific shop drawings and
- product data sheets.

General Note
Drawing prov based on ori
to verify all d

General: The following notes are intended to illustrate general locations of typical work items included in the base bid, and are not intended to be a complete scope of work. Refer to the project specifications for complete description of all work to be performed. For simplification, work items pertaining to the "original building" are noted as "OB", while work pertaining to the newer addition are noted as "NA".

- **1. NA:** Remove and replace thru-wall flashing at the stone tower with new. Refer to Detail D7/A501. [Approx. 15 LF]
- (2.) NA: Remove and replace thru-wall flashing along penthouse with new. Refert to Detail D9/A501. [Approx. 70 LF]
- $\langle 3. \rangle$ **OB:** Perform metal roof repairs, which includes providing new flashing at the aluminum cladded battens with proper detailing at transition points, providing new fasteners, with washers, to aluminum cladded battens, providing a watertight barrier at the transition from the existing BUR to metal sloped roof, and sealing exposed joints in the metal panels. Refer to Detail D25/A504.
- $\langle 4. \rangle$  **OB:** Re-secure existing snowguards (all elevations). [Approx. 315 LF]. Refer to Detail D29/A504.
- **5. NA:** Remove and replace existing window thru-wall flashing with new. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Details D13/A502 & D14/502. [Approx. 180 LF]
- $\langle 6. \rangle$  NA: Remove and replace existing shelf angles. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Detail D8/A501. [Approx. 230 LF]
- (7.) NA: Remove and replace control joints with new. Refer to Details D3/A500 & D12/A502. [Approx. 2,150 LF]
- (8.) NA: Remove and replace window perimeter sealants with new. Refer to Details D3/A500 & D12/A502. [Approx. 1,380 LF]
- (9.) NA: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Details D1/A500 & D2/A500. [Approx. 500 SF]
- (10) NA: Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 16 units].
- (11) **OB:** Remove and replace window perimeter sealants. Refer to Details D3/A500 & D12/A502. [Approx. 18,120 LF]
- (12) OB: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Detail D1/A500 [Approx. 16,410 SF general & 1,014 SF severe deterioration]. Provide a unit price for localized and isolated repairs.
- (13) **OB:** Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 251 units]. Provide a unit price for localized and isolated repairs.
- (14) OB: Rout and seal cracks in the brick and stone walls. Refer to Details D7/A501, D8/A501 & D9/501. [Approx. 185 LF]. Provide a unit price for localized and isolated repairs.
- (15) **OB:** Repair damaged and/or spalled stone in the limestone bands using Dutchman style repairs. Refer to Details D21/A503, D22/A503 & D23/A503. [Approx. 54 SF]. Provide a unit price for localized and isolated repairs.
- (16) OB: Repair damaged and/or spalled terracotta stone. Refer to Detail D18/A503. [Approx. 122 SF]. Provide a unit price for localized and isolated repairs.
- (17) OB: Rout and seal cracks in the terracotta stone. Refer to Detail D19/A503. [Approx. 48 LF]. Provide a unit price for localized and isolated repairs.
- (18) OB: If heavy rust pack and section loss is visible in the window lintel, remove and replace existing lintels with new and associated flashing above windows. If surface corrosion with no section loss is visible, clean and paint existing lintels. Refer to Details D10/A501 & D11/A501. [Approx. 953 LF]
- (19) OB: If heavy rust pack and section loss is visible in the shelf angles, remove and replace existing shelf angles with new and associated flashing. If surface corrosion with no section loss is visible, clean and paint existing shelf angles. Similar to Detail D8/A501. [Approx. 186 LF]
- (20) OB: Repairs to the courtyard terrace concrete steps. Refer to Detail D17/A502. Allow for lump sum of \$10,000.
- $\langle 21 \rangle$  OB: Repairs to the spalled concrete retaining wall on the west elevation of the original building. Refer to Detail D21/503. Allow for lump sum of \$10,000.
- (22) OB: Repairs to the damaged keystone arch at the west elevation entrance. Refer to Detail D24/A504. Allow for lump sum of \$20,000.
- (23) **OB:** Re-securement and/or replacement of the copper flashing. Refer to Detail D23/A503. [Approx. 15 LF]. Allow for lump sum of \$15,000.

DRAWN APPRO REVISE APPRO REVISE APPRO APPRO ISSUED FO	INT VED D 1 5 VED D 2 VED D 3 VED ED FOR 1 DR BID	11/1 11/1 50% CHE 1/24 BIDS 2/20	/2024 /2024 CK SET /2025
WAYNE STATE UNIVERSITY	<b>OLD MAIN BUILDING - NEW ADDITION</b>	WSU PROJECT #001-400580	SOUTH ELEVATION
	Building Science Solutions	Building and Construction	200-45000 Helm Street · Plymouth · Michigan · 481 70 · Tel 248 957.9911

INITIALS/DATE



A-103

3. Permits: Contractor shall secure any required permits prior to proceeding with any work and shall coordinate building inspections with the Owner, including the WSU Fire Inspector.

DWG FRE OTANELOLDWG

vided are approximate scale riginal design drawings. Contractor limensions.

P'HSE FLOOR EL .: 177'--7" 157'--7" FOURTH FLOOR EL .: THIRD FLOOR EL .: 145'-2" -ALUM. CURTAINWALL W/TINTED INSUL, GLASS OR SPANDREL GLASS (WHERE SHOWN SHADED) -STONE PANELS 131'-7" SECOND FLOOR EL .: - FACE BRICK - EXPANSION JOINT - ALUM. DOORS/FRAME FIRST FLOOR EL .: 114'-0" BSMT. FLOOR EL .: 100'---0". PRO.ECT # : 33010.01





SCALE: N.T.S.

$\bigotimes$	SEVERE BRICK REPOINTING	<b>A</b> #	DAMAGED BRICK (# = NO. OF BRICKS)		DAMAGED/MISSING LIMESTONE		SPALLED/DAMAGED TERRACOTTA	CONTROL JOINT
	CRACKED BRICK/STONE		DAMAGED SHELF ANGLE/LINTEL	۲ ۲ ۲	CRACKED LIMESTONE	ξT	CRACKED TERRACOTTA	

NOTE: THE SYMBOLS SHOWN ARE USED ON OUR DRAWINGS TO INDICATE ROOF FEATURES ADDITIONAL SYMBOLS MAY BE SHOWN ON THE DRAWING FOR SPECIFIC PROJECTS.

1. Drawings and specifications are intended to be a schematic representation of the existing conditions and overall design intent. Contractor is responsible to review existing conditions and develop the specific scope of work for the project, which shall meet the design intent as well as be in accordance with all applicable building codes.

2. Contractor shall submit a developed and complete scope of work document, including project specific shop drawings and product data sheets.

3. Permits: Contractor shall secure any required permits prior to proceeding with any work and shall coordinate building inspections with the Owner, including the WSU Fire Inspector.

Drawing provided are approximate scale based on original design drawings. Contractor to verify all dimensions.

General Note:

General: The following notes are intended to illustrate general locations of typical work items included in the base bid, and are not intended to be a complete scope of work. Refer to the project specifications for complete description of all work to be performed. For simplification, work items pertaining to the "original building" are noted as "OB", while work pertaining to the newer addition are noted as "NA".

- (1.) **NA:** Remove and replace thru-wall flashing at the stone tower with new. Refer to Detail D7/A501. [Approx. 15 LF]
- (2.) NA: Remove and replace thru-wall flashing along penthouse with new. Refert to Detail D9/A501. [Approx. 70 LF]
- $\overline{(3.)}$  OB: Perform metal roof repairs, which includes providing new flashing at the aluminum cladded battens with proper detailing at transition points, providing new fasteners, with washers, to aluminum cladded battens, providing a watertight barrier at the transition from the existing BUR to metal sloped roof, and sealing exposed joints in the metal panels. Refer to Detail D25/A504.
- $\langle 4. \rangle$  **OB:** Re-secure existing snowguards (all elevations). [Approx. 315 LF]. Refer to Detail D29/A504.
- $\overline{(5.)}$  NA: Remove and replace existing window thru-wall flashing with new. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Details D13/A502 & D14/502. [Approx. 180 LF]
- **6. NA:** Remove and replace existing shelf angles. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Detail D8/A501. [Approx. 230 LF]
- (7.) NA: Remove and replace control joints with new. Refer to Details D3/A500 & D12/A502. [Approx. 2,150 LF]
- $\langle 8. \rangle$  NA: Remove and replace window perimeter sealants with new. Refer to Details D3/A500 & D12/A502. [Approx. 1,380 LF]
- $\langle 9. \rangle$  NA: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Details D1/A500 & D2/A500. [Approx. 500 SF]
- $\langle 10 \rangle$  NA: Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 16 units].
- (11) **OB:** Remove and replace window perimeter sealants. Refer to Details D3/A500 & D12/A502. [Approx. 18,120 LF]
- (12) OB: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Detail D1/A500 [Approx. 16,410 SF general & 1,014 SF severe deterioration]. Provide a unit price for localized and isolated repairs.
- $\langle 13 \rangle$  OB: Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 251 units]. Provide a unit price for localized and isolated repairs.
- $\langle 14 \rangle$  OB: Rout and seal cracks in the brick and stone walls. Refer to Details D7/A501, D8/A501 & D9/501. [Approx. 185 LF]. Provide a unit price for localized and isolated repairs.
- (15) OB: Repair damaged and/or spalled stone in the limestone bands using Dutchman style repairs. Refer to Details D21/A503, D22/A503 & D23/A503. [Approx. 54 SF]. Provide a unit price for localized and isolated repairs.
- (16) OB: Repair damaged and/or spalled terracotta stone. Refer to Detail D18/A503. [Approx. 122 SF]. Provide a unit price for localized and isolated repairs.
- (17) OB: Rout and seal cracks in the terracotta stone. Refer to Detail D19/A503. [Approx. 48 LF]. Provide a unit price for localized and isolated repairs.
- $\langle 18 \rangle$  OB: If heavy rust pack and section loss is visible in the window lintel, remove and replace existing lintels with new and associated flashing above windows. If surface corrosion with no section loss is visible, clean and paint existing lintels. Refer to Details D10/A501 & D11/A501. [Approx. 953 LF]
- (19) OB: If heavy rust pack and section loss is visible in the shelf angles, remove and replace existing shelf angles with new and associated flashing. If surface corrosion with no section loss is visible, clean and paint existing shelf angles. Similar to Detail D8/A501. [Approx. 186 LF]
- $\langle 20 \rangle$  OB: Repairs to the courtyard terrace concrete steps. Refer to Detail D17/A502. Allow for lump sum of \$10,000.
- $\langle 21 \rangle$  OB: Repairs to the spalled concrete retaining wall on the west elevation of the original building. Refer to Detail D21/503. Allow for lump sum of \$10,000.
- $\langle 22 \rangle$  OB: Repairs to the damaged keystone arch at the west elevation entrance. Refer to Detail D24/A504. Allow for lump sum of \$20,000.
- (23) **OB:** Re-securement and/or replacement of the copper flashing. Refer to Detail D23/A503. [Approx. 15 LF]. Allow for lump sum of \$15,000.

INITIALS/DATE DRAWN INT 50% CHECK SET APPROVED 1/24/2025 REVISED 1 APPROVED REVISED 2 APPROVED REVISED 3 APPROVED APPROVED FOR BIDS ISSUED FOR BID 2/20/2025











NOTE: THE SYMBOLS SHOWN ARE USED ON OUR DRAWINGS TO INDICATE ROOF FEATURES. ADDITIONAL SYMBOLS MAY BE SHOWN ON THE DRAWING FOR SPECIFIC PROJECTS.

based on original design drawings. Contractor to verify all dimensions.

General: The following notes are intended to illustrate general locations of typical work items included in the base bid, and are not intended to be a complete scope of work. Refer to the project specifications for complete description of all work to be performed. For simplification, work items pertaining to the "original building" are noted as "OB", while work pertaining to the newer addition are noted as "NA".

(1.) NA: Remove and replace thru-wall flashing at the stone tower with new. Refer to Detail D7/A501. [Approx. 15 LF]

- (2.) NA: Remove and replace thru-wall flashing along penthouse with new. Refert to Detail D9/A501. [Approx. 70 LF]
- (3.) **OB:** Perform metal roof repairs, which includes providing new flashing at the aluminum cladded battens with proper detailing at transition points, providing new fasteners, with washers, to aluminum cladded battens, providing a watertight barrier at the transition from the existing BUR to metal sloped roof, and sealing exposed joints in the metal panels. Refer to Detail D25/A504.
- $\langle 4. \rangle$  **OB:** Re-secure existing snowguards (all elevations). [Approx. 315 LF]. Refer to Detail D29/A504.
- $\overline{(5.)}$  **NA:** Remove and replace existing window thru-wall flashing with new. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Details D13/A502 & D14/502. [Approx. 180 LF]
- $\widehat{(6.)}$  NA: Remove and replace existing shelf angles. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Detail D8/A501. [Approx. 230 LF]
- **7. NA:** Remove and replace control joints with new. Refer to Details D3/A500 & D12/A502. [Approx. 2,150 LF]
- $\langle 8. \rangle$  NA: Remove and replace window perimeter sealants with new. Refer to Details D3/A500 & D12/A502. [Approx. 1,380 LF]
- $\langle 9. \rangle$  NA: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Details D1/A500 & D2/A500. [Approx. 500 SF]
- $(\mathbf{10}, \mathbf{NA}: \mathbf{Remove} \text{ and replace spalled brick. Brick that is})$ missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 16 units].
- (11) OB: Remove and replace window perimeter sealants. Refer to Details D3/A500 & D12/A502. [Approx. 18,120 LF]
- (12) OB: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Detail D1/A500 [Approx. 16,410 SF general & 1,014 SF severe deterioration]. Provide a unit price for localized and isolated repairs.
- (13) **OB:** Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 251 units]. Provide a unit price for localized and isolated repairs.
- (14) OB: Rout and seal cracks in the brick and stone walls. Refer to Details D7/A501, D8/A501 & D9/501. [Approx. 185 LF]. Provide a unit price for localized and isolated repairs.
- (15) OB: Repair damaged and/or spalled stone in the limestone bands using Dutchman style repairs. Refer to Details D21/A503, D22/A503 & D23/A503. [Approx. 54 SF]. Provide a unit price for localized and isolated repairs.
- (16) OB: Repair damaged and/or spalled terracotta stone. Refer to Detail D18/A503. [Approx. 122 SF]. Provide a unit price for localized and isolated repairs.
- (17) **OB:** Rout and seal cracks in the terracotta stone. Refer to Detail D19/A503. [Approx. 48 LF]. Provide a unit price for localized and isolated repairs.
- (18) OB: If heavy rust pack and section loss is visible in the window lintel, remove and replace existing lintels with new and associated flashing above windows. If surface corrosion with no section loss is visible, clean and paint existing lintels. Refer to Details D10/A501 & D11/A501. [Approx. 953 LF]
- (19) OB: If heavy rust pack and section loss is visible in the shelf angles, remove and replace existing shelf angles with new and associated flashing. If surface corrosion with no section loss is visible, clean and paint existing shelf angles. Similar to Detail D8/A501. [Approx. 186 LF]
- (20) OB: Repairs to the courtyard terrace concrete steps. Refer to Detail D17/A502. Allow for lump sum of \$10,000.
- $\langle 21 \rangle$  OB: Repairs to the spalled concrete retaining wall on the west elevation of the original building. Refer to Detail D21/503. Allow for lump sum of \$10,000.
- (22) OB: Repairs to the damaged keystone arch at the west elevation entrance. Refer to Detail D24/A504. Allow for lump sum of \$20,000.
- (23) **OB:** Re-securement and/or replacement of the copper flashing. Refer to Detail D23/A503. [Approx. 15 LF]. Allow for lump sum of \$15,000.

INITIALS/DATE DRAWN INT 50% CHECK SET 1/24/2025 APPROVED REVISED 1 APPROVED REVISED 2 APPROVED REVISED 3 APPROVED APPROVED FOR BIDS ISSUED FOR BID 2/20/2025



) Science Solution ) and Constructior • Michigan • 481 70 · Tel 248 957,991 Building Building S









NORTH ELEVATION - TOWER (12) (A-106) SCALE: N.T.S

- 1. Drawings and spe representation of intent. Contractor and develop the shall meet the de applicable buildir
- 2. Contractor shall s work document, product data she
- 3. Permits: Contract proceeding with inspections with

### General Note

Drawing prov to verify all dimensions.

	SYMBOL LEGEND								
$\boxtimes$	SEVERE BRICK REPOINTING	<b>▲</b> #	DAMAGED BRICK (# = NO. OF BRICKS)		DAMAGED/MISSING LIMESTONE		SPALLED/DAMAGED TERRACOTTA		CONTROL JOINT
<u> </u>	CRACKED BRICK/STONE		DAMAGED SHELF ANGLE/LINTEL	ξL	CRACKED LIMESTONE	ξT	CRACKED TERRACOTTA		

**NOTE:** THE SYMBOLS SHOWN ARE USED ON OUR DRAWINGS TO INDICATE ROOF FEATURES. ADDITIONAL SYMBOLS MAY BE SHOWN ON THE DRAWING FOR SPECIFIC PROJECTS.

	SLOPED ALLIMINUM SUSET DOOF (T)
	- SEE ROOF PLAN SHT. 43
	TERRA COTTA COPING / TRIM
	CLOCK WITH TERRA COTTA TRIM
	ORNATE COPPER CLAD WOOD CORNI GUTTER
	TERRA COTTA TRIM
	STONE TRIM
4	FACE BRICK CHIMNEY W/ STONE CA
	ORNATE COPPER CLAD WOOD FRAME
	DOOR / FRAME WITH STAIR
	FLAT BUILT-UP ROOF (TYPE II)
TYP.	TERRA COTTA COPING / TRIM
$A \diamond$	YP.
13	CORNICE / GUTTER WITH TERRA COTTA TRIM BELOW
4	TERRA COTTA TRIM
-	FACE BRICK - TYPICAL WALL FACING
	TERRA COTTA TRIM / WINDOW SILL
	TERRA COTTA WINDOW TRIM - TYP. AT FIRST FLOOR (1907 ADDITION)
	STONE TRIM / WINDOW SILL
	(*************************************
	STONE TRIM / WINDOW SHI
TYP.	STORE IKIM / WINDOW SILL
	The second se
Drowings	officiations are intended to be such as all
representation of intent. Contractor and develop the s shall meet the des applicable buildin	the existing conditions and overall design is responsible to review existing conditions pecific scope of work for the project, which sign intent as well as be in accordance with all g codes.
Contractor shall su work document, in product data shee	ubmit a developed and complete scope of ncluding project specific shop drawings and ets.
Permits: Contractor proceeding with a inspections with t	or shall secure any required permits prior to any work and shall coordinate building he Owner, including the WSU Fire Inspector.
General Note	
Drawing provi	ded are approximate scale
based on orig	inal design drawings.Contractor

General: The following notes are intended to illustrate general ocations of typical work items included in the base bid, and are not intended to be a complete scope of work. Refer to the project specifications for complete description of all work to be erformed. For simplification, work items pertaining to the priginal building" are noted as "OB", while work pertaining to he newer addition are noted as "NA".

- **NA:** Remove and replace thru-wall flashing at the stone tower with new. Refer to Detail D7/A501. [Approx. 15 LF]
- **NA:** Remove and replace thru-wall flashing along penthouse with new. Refert to Detail D9/A501. [Approx. 70 LF]
- **OB:** Perform metal roof repairs, which includes providing new flashing at the aluminum cladded battens with proper detailing at transition points, providing new fasteners, with washers, to aluminum cladded battens, providing a watertight barrier at the transition from the existing BUR to metal sloped roof, and sealing exposed joints in the metal panels. Refer to Detail D25/A504.
- **OB:** Re-secure existing snowguards (all elevations). [Approx. 315 LF]. Refer to Detail D29/A504.
- **NA:** Remove and replace existing window thru-wall flashing with new. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Details D13/A502 & D14/502. [Approx. 180 LF]
- **NA:** Remove and replace existing shelf angles. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Detail D8/A501. [Approx. 230 LF]
- **NA:** Remove and replace control joints with new. Refer to Details D3/A500 & D12/A502. [Approx. 2,150 LF]
- **NA:** Remove and replace window perimeter sealants with new. Refer to Details D3/A500 & D12/A502. [Approx. 1,380 LF]
- **NA:** Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Details D1/A500 & D2/A500. [Approx. 500 SF]
- **0) NA:** Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 16 units].
- **OB:** Remove and replace window perimeter sealants. Refer to Details D3/A500 & D12/A502. [Approx. 18,120 LF]
- 2) **OB:** Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Detail D1/A500 [Approx. 16,410 SF general & 1,014 SF severe deterioration]. Provide a unit price for localized and isolated repairs.
- 3) **OB:** Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 251 units]. Provide a unit price for localized and isolated repairs.
- **4COB:** Rout and seal cracks in the brick and stone walls. Refer to Details D7/A501, D8/A501 & D9/501. [Approx. 185 LF]. Provide a unit price for localized and isolated repairs.
- **OB:** Repair damaged and/or spalled stone in the limestone bands using Dutchman style repairs. Refer to Details D21/A503, D22/A503 & D23/A503. [Approx. 54 SF]. Provide a unit price for localized and isolated repairs.
- **OB:** Repair damaged and/or spalled terracotta stone. Refer to Detail D18/A503. [Approx. 122 SF]. Provide a unit price for localized and isolated repairs.
- (17) **OB:** Rout and seal cracks in the terracotta stone. Refer to Detail D19/A503. [Approx. 48 LF]. Provide a unit price for localized and isolated repairs.
- (18) OB: If heavy rust pack and section loss is visible in the window lintel, remove and replace existing lintels with new and associated flashing above windows. If surface corrosion with no section loss is visible, clean and paint existing lintels. Refer to Details D10/A501 & D11/A501. [Approx. 953 LF]
- (19) OB: If heavy rust pack and section loss is visible in the shelf angles, remove and replace existing shelf angles with new and associated flashing. If surface corrosion with no section loss is visible, clean and paint existing shelf angles. Similar to Detail D8/A501. [Approx. 186 LF]
- (20) OB: Repairs to the courtyard terrace concrete steps. Refer to Detail D17/A502. Allow for lump sum of \$10,000.
- (21) OB: Repairs to the spalled concrete retaining wall on the west elevation of the original building. Refer to Detail D21/503. Allow for lump sum of \$10,000.
- (22) **OB:** Repairs to the damaged keystone arch at the west elevation entrance. Refer to Detail D24/A504. Allow for lump sum of \$20,000.
- (23) **OB:** Re-securement and/or replacement of the copper flashing. Refer to Detail D23/A503. [Approx. 15 LF]. Allow for lump sum of \$15,000.

	١١	NITIALS	JATE
DRAW	N INT	50% CH	ECK SET
APPR	DVED	1/2	4/2025
REVIS	ED 1		
APPR(	DVED		
REVIS	ED 2		
APPR	 DVED		
APPRO	/ED FOR	BIDS	
ISSUED I	FOR BID	2/2	0/2025
WAYNE STATE UNIVERSITY	OLD MAIN BUILDING	WSU PROJECT #001-400580	ORIGINAL BUILDING - NORTH ELEVATION
	Building Science Solutions	Building and Construction	200-45000 Helm Street · Plymouth · Michigan · 481 70 · Tel 248 957.991 1
		YNE STATE	



-	- SLOPED ALUMINUM SHEET ROOF (TYPE 1) - SEE ROOF PLAN SHT. 43
	- TERRA COTTA COPING / TRIM
/	- CLOCK WITH TERRA COTTA TRIM SURROUND
-	- ORNATE COPPER CLAD WOOD CORNICE GUTTER
	- TERRA COTTA TRIM
-	- STONE TRIM
TYP.	ALUMINUM SHEET CLAD CUPOLA WITH PERIMETER ALUMINUM LOUVERS TYPICAL
	ORNATE COPPER CLAD WOOD FRAMED BALCONY
	TERRA COTTA COPING / TRIM
	SLOPED ALUMINUM SHEET ROOF (TYPE 1) - SEE ROOF PLAN
	ORNATE ALUMINUM CLAD WOOD
	TERRA COTTA TRIM
-	STONE TRIM / WINDOW SILL
	FACE BRICK - TYPICAL UPPER FLOOR WALL FACING MATERIAL
	ORNATE FACE BRICK WINDOW SURROUNDS - TYPICAL
	ASHLAR STONE MASONRY
	STONE TRIM / WINDOW SILL
	ASHLAR STONE MASONRY - TYPICAL BASEMENT FLOOR WALL FACING MATERI

	5
2. Contrac work do product	tor shall sub ocument, inc t data sheets
3. Permits	Contractor

1. Drawings and specifications are intended to be a schematic representation of the existing conditions and overall design intent. Contractor is responsible to review existing conditions and develop the specific scope of work for the project, which shall meet the design intent as well as be in accordance with all

> omit a developed and complete scope of cluding project specific shop drawings and

shall secure any required permits prior to proceeding with any work and shall coordinate building inspections with the Owner, including the WSU Fire Inspector.

Drawing provided are approximate scale based on original design drawings. Contractor General: The following notes are intended to illustrate general locations of typical work items included in the base bid, and are not intended to be a complete scope of work. Refer to the project specifications for complete description of all work to be performed. For simplification, work items pertaining to the "original building" are noted as "OB", while work pertaining to the newer addition are noted as "NA".

(1.) **NA:** Remove and replace thru-wall flashing at the stone tower with new. Refer to Detail D7/A501. [Approx. 15 LF]

- (2.) NA: Remove and replace thru-wall flashing along penthouse with new. Refert to Detail D9/A501. [Approx. 70 LF]
- OB: Perform metal roof repairs, which includes providing < **3.**) new flashing at the aluminum cladded battens with proper detailing at transition points, providing new fasteners, with washers, to aluminum cladded battens, providing a watertight barrier at the transition from the existing BUR to metal sloped roof, and sealing exposed joints in the metal panels. Refer to Detail D25/A504.
- $\overline{(4.)}$  **OB:** Re-secure existing snowguards (all elevations). [Approx. 315 LF]. Refer to Detail D29/A504.
- $\overline{(5.)}$  NA: Remove and replace existing window thru-wall flashing with new. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Details D13/A502 & D14/502. [Approx. 180 LF]
- **6. NA:** Remove and replace existing shelf angles. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Detail D8/A501. [Approx. 230 LF]
- $\overline{(7.)}$  NA: Remove and replace control joints with new. Refer to Details D3/A500 & D12/A502. [Approx. 2,150 LF]
- (8.) NA: Remove and replace window perimeter sealants with new. Refer to Details D3/A500 & D12/A502. [Approx. 1,380 LF]
- $\overline{(9.)}$  NA: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Details D1/A500 & D2/A500. [Approx. 500 SF]
- (10.) NA: Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 16 units].
- (11) OB: Remove and replace window perimeter sealants. Refer to Details D3/A500 & D12/A502. [Approx. 18,120 LF]
- (12) OB: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Detail D1/A500 [Approx. 16,410 SF general & 1,014 SF severe deterioration]. Provide a unit price for localized and isolated repairs.
- (13) OB: Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 251 units]. Provide a unit price for localized and isolated repairs.
- $\langle \mathbf{14} \rangle$  **OB:** Rout and seal cracks in the brick and stone walls. Refer to Details D7/A501, D8/A501 & D9/501. [Approx. 185 LF]. Provide a unit price for localized and isolated repairs.
- (15) OB: Repair damaged and/or spalled stone in the limestone bands using Dutchman style repairs. Refer to Details D21/A503, D22/A503 & D23/A503. [Approx. 54 SF]. Provide a unit price for localized and isolated repairs.
- (16) OB: Repair damaged and/or spalled terracotta stone. Refer to Detail D18/A503. [Approx. 122 SF]. Provide a unit price for localized and isolated repairs.
- (17) **OB:** Rout and seal cracks in the terracotta stone. Refer to Detail D19/A503. [Approx. 48 LF]. Provide a unit price for localized and isolated repairs.
- (18.) OB: If heavy rust pack and section loss is visible in the window lintel, remove and replace existing lintels with new and associated flashing above windows. If surface corrosion with no section loss is visible, clean and paint existing lintels. Refer to Details D10/A501 & D11/A501. [Approx. 953 LF]
- (19) OB: If heavy rust pack and section loss is visible in the shelf angles, remove and replace existing shelf angles with new and associated flashing. If surface corrosion with no section loss is visible, clean and paint existing shelf angles. Similar to Detail D8/A501. [Approx. 186 LF]
- $\langle 20 \rangle$  OB: Repairs to the courtyard terrace concrete steps. Refer to Detail D17/A502. Allow for lump sum of \$10,000.
- (21) OB: Repairs to the spalled concrete retaining wall on the west elevation of the original building. Refer to Detail D21/503. Allow for lump sum of \$10,000.
- (22) OB: Repairs to the damaged keystone arch at the west elevation entrance. Refer to Detail D24/A504. Allow for lump sum of \$20,000.
- (23) **OB:** Re-securement and/or replacement of the copper flashing. Refer to Detail D23/A503. [Approx. 15 LF]. Allow for lump sum of \$15,000.

	I	NITI	ALS/D	ATE
RAWN	INT	50%	CHECK	SET
APPROVE	D		1/24/2	025
REVISED	1			
APPROVE	D			
REVISED	2			
APPROVE	D			
REVISED	3			
APPROVE	D			
PPROVED	FOR	BID	S	
SSUED FOR	BID		2/20/2	025

OLD MAIN BUILDING	WSU PROJECT #001-400580	<b>OPIGINAL BUILDING - SOUTH ELEVATION</b>
-------------------	-------------------------	--











## GENERAL NOTES:

- applicable building codes.
- product data sheets.

# General Note:

Drawing provide based on origin to verify all dime

# **COURTYARD - SOUTH ELEVATION**







PROVIDE CONCRETE PLA DETAINING WALLS (CONT

CONC. (20) COURTYARD

LANDING

TO DETAIL D14/A502

**REPAIRS. REFER** 

	SYMBOL LEGEND									
X	SEVERE BRICK REPOINTING	<b>A</b> #	DAMAGED BRICK (# = NO. OF BRICKS)		DAMAGED/MISSING LIMESTONE		SPALLED/DAMAGED TERRACOTTA	— —	CONTROL JOINT	
	CRACKED BRICK/STONE		DAMAGED SHELF ANGLE/LINTEL	ξL	CRACKED LIMESTONE	ξT	CRACKED TERRACOTTA			

**NOTE:** THE SYMBOLS SHOWN ARE USED ON OUR DRAWINGS TO INDICATE ROOF FEATURES. ADDITIONAL SYMBOLS MAY BE SHOWN ON THE DRAWING FOR SPECIFIC PROJECTS.

1. Drawings and specifications are intended to be a schematic representation of the existing conditions and overall design intent. Contractor is responsible to review existing conditions and develop the specific scope of work for the project, which shall meet the design intent as well as be in accordance with all

2. Contractor shall submit a developed and complete scope of work document, including project specific shop drawings and

3. Permits: Contractor shall secure any required permits prior to proceeding with any work and shall coordinate building inspections with the Owner, including the WSU Fire Inspector.

ed are approximate	scale
al design drawings.	Contractor
ensions.	

General: The following notes are intended to illustrate general locations of typical work items included in the base bid, and are not intended to be a complete scope of work. Refer to the project specifications for complete description of all work to be performed. For simplification, work items pertaining to the "original building" are noted as "OB", while work pertaining to the newer addition are noted as "NA".

- (1.) NA: Remove and replace thru-wall flashing at the stone tower with new. Refer to Detail D7/A501. [Approx. 15 LF]
- (2.) NA: Remove and replace thru-wall flashing along penthouse with new. Refert to Detail D9/A501. [Approx. 70 LF]
- (3.) **OB:** Perform metal roof repairs, which includes providing new flashing at the aluminum cladded battens with proper detailing at transition points, providing new fasteners, with washers, to aluminum cladded battens, providing a watertight barrier at the transition from the existing BUR to metal sloped roof, and sealing exposed joints in the metal panels. Refer to Detail D25/A504.
- $\langle 4. \rangle$  **OB:** Re-secure existing snowguards (all elevations). [Approx. 315 LF]. Refer to Detail D29/A504.
- $\langle 5. \rangle$  NA: Remove and replace existing window thru-wall flashing with new. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Details D13/A502 & D14/502. [Approx. 180 LF]
- **6. NA:** Remove and replace existing shelf angles. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Detail D8/A501. [Approx. 230 LF]
- (7.) NA: Remove and replace control joints with new. Refer to Details D3/A500 & D12/A502. [Approx. 2,150 LF]
- (8.) NA: Remove and replace window perimeter sealants with new. Refer to Details D3/A500 & D12/A502. [Approx. 1,380 LF]
- (9.) NA: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Details D1/A500 & D2/A500. [Approx. 500 SF]
- $\langle 10 \rangle$  NA: Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 16 units].
- (11) **OB:** Remove and replace window perimeter sealants. Refer to Details D3/A500 & D12/A502. [Approx. 18,120 LF]
- (12) OB: Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Detail D1/A500 [Approx. 16,410 SF general & 1,014 SF severe deterioration]. Provide a unit price for localized and isolated repairs.
- (13) OB: Remove and replace spalled brick. Brick that is missing shall be replaced with new. Refer to Detail D2/A500 [Approx. 251 units]. Provide a unit price for localized and isolated repairs.
- (14) **OB:** Rout and seal cracks in the brick and stone walls. Refer to Details D7/A501, D8/A501 & D9/501. [Approx. 185 LF]. Provide a unit price for localized and isolated repairs.
- (15) OB: Repair damaged and/or spalled stone in the limestone bands using Dutchman style repairs. Refer to Details D21/A503, D22/A503 & D23/A503. [Approx. 54 SF]. Provide a unit price for localized and isolated repairs.
- (16) **OB:** Repair damaged and/or spalled terracotta stone. Refer to Detail D18/A503. [Approx. 122 SF]. Provide a unit price for localized and isolated repairs.
- (17) **OB:** Rout and seal cracks in the terracotta stone. Refer to Detail D19/A503. [Approx. 48 LF]. Provide a unit price for localized and isolated repairs.
- (18) OB: If heavy rust pack and section loss is visible in the window lintel, remove and replace existing lintels with new and associated flashing above windows. If surface corrosion with no section loss is visible, clean and paint existing lintels. Refer to Details D10/A501 & D11/A501. [Approx. 953 LF]
- $\langle 19 \rangle$  OB: If heavy rust pack and section loss is visible in the shelf angles, remove and replace existing shelf angles with new and associated flashing. If surface corrosion with no section loss is visible, clean and paint existing shelf angles. Similar to Detail D8/A501. [Approx. 186 LF]
- $\langle 20 \rangle$  OB: Repairs to the courtyard terrace concrete steps. Refer to Detail D17/A502. Allow for lump sum of \$10,000.
- (21) OB: Repairs to the spalled concrete retaining wall on the west elevation of the original building. Refer to Detail D21/503. Allow for lump sum of \$10,000.
- (22) OB: Repairs to the damaged keystone arch at the west elevation entrance. Refer to Detail D24/A504. Allow for lump sum of \$20,000.
- (23) **OB:** Re-securement and/or replacement of the copper flashing. Refer to Detail D23/A503. [Approx. 15 LF]. Allow for lump sum of \$15,000.

	11	NITIA	ALS/D/	٩ΤΕ
DRAWN	INT	50%	CHECK	SET
APPROVE	D		1/24/20	025
REVISED	1			
APPROVE	D			
REVISED	2			
APPROVE	D			
REVISED	3			
APPROVE	D			
PPROVED	FOR	BIDS	5	
SSUED FOR	BID		2/20/2	025













- FIELD.
- AND REPLACED TO A DEPTH OF 3" MAXIMUM. DO NOT OVERCUT OR DAMAGE EDGES OF ADJACENT MASONRY.
- (  $_{03}$  ) CLEAN AND REPOINT THE EXISTING EXPOSED BACK-UP WALL WHERE EXTENTS OF LOCALIZED BRICK REBUILD EXCEEDS 2SF. INSTALL NEW STAINLESS STEEL WALL TIES AT A MIN. OF 1 PER 1.5 SF. NOTIFY ENGINEER WHERE CRACKING APPEARS TO EXTEND THROUGH BACK-UP MASONRY. DO NOT REPLACE HEADER BRICKS IF NOT CRACKED.
- INSTALLED WITH TYPE N MORTAR. NEW BRICK MUST BE REVIEWED AND THE SIZE, SHAPE, TEXTURE AND COLOR OF THE EXISTING BRICK. PLACE THE NEW BRICK TO MATCH THE ADJACENT SURROUNDING COURSING.
- (05) RAKE THE MORTAR JOINTS ON ALL FOUR SIDES OF THE NEWLY INSTALLED REPLACEMENT BRICK AT 1.5" PAST THE OUTSIDE FACE. ALLOW THE SETTING MORTAR TO CURE FOR 24 HOURS PRIOR TO POINTING THE JOINTS WITH THE APPROVED MORTAR FOLLOWING THE REQUIREMENTS OF THE TYPICAL MASONRY REPOINTING DETAIL







![](_page_14_Picture_12.jpeg)

![](_page_14_Figure_13.jpeg)

TYPICAL LINTEL REPLACEMENT DETAIL AT ORIGINAL BUILDING - STONE

![](_page_15_Picture_0.jpeg)

![](_page_16_Figure_0.jpeg)

![](_page_16_Picture_1.jpeg)

CONC. STAIRS & SLAB - CURRENT CONDITION

D18

A-503

D21 A-503

![](_page_16_Figure_3.jpeg)

![](_page_16_Figure_4.jpeg)

D19 A-503

D22 A-503

![](_page_16_Figure_6.jpeg)

![](_page_16_Figure_9.jpeg)

![](_page_16_Figure_10.jpeg)

![](_page_16_Figure_12.jpeg)

![](_page_17_Picture_0.jpeg)

![](_page_17_Picture_6.jpeg)

![](_page_17_Picture_8.jpeg)

![](_page_17_Picture_9.jpeg)

# WAYNE STATE UNIVERSITY **STUDENT CENTER BUILDING - ENCLOSURE REPAIRS** WSU PROJECT # 034-350347

![](_page_18_Figure_1.jpeg)

Scale: N.T.S.

![](_page_18_Figure_3.jpeg)

![](_page_18_Picture_4.jpeg)

	INITIALS/DATE 11/11/2024 11/11/2024	
REVISED 1 APPROVED REVISED 2 APPROVED REVISED 3 APPROVED APPROVED FOR ISSUED FOR BID	50% CD 12/19/2024 90% CD 2/5/2025 R BIDS 2/20/2025	
WAYNE STATE UNIVERSITY STUDENT CENTER	WSU PROJECT #034-350347	
Building Science Solutions Building and Construction 200-4500 Helm Street - Plymouth - Michigan - 481 70. Tel 248, 957, 991		

![](_page_19_Picture_0.jpeg)

AVENUE

![](_page_19_Picture_2.jpeg)

# - TEMPORARY STAGING PERMITTED ALONG GULLEN MALL AND KIRBY ST. COORDINATE WITH WSU PROJECT MANAGER FOR LOCATION. LIFT STAGING ONLY. NO SCAFFOLDING IS PERMITTED.

ENTRY/EXIT POINT AT 3rd

![](_page_19_Picture_5.jpeg)

SITE PLAN NOT TO SCALE

# - STAGING AREA. COORDINATE WITH WSU PROJECT MANAGER FOR TRAFFIC AND EXACT LOCATION.

DUMPSTER AREA

GENERAL NOTES:

- Drawings and specifications are intended to be a schematic representation of the existing conditions and overall design intent. Contractor is responsible to review existing conditions and develop the specific scope of work for the project, which shall meet the design intent as well as be in accordance with all applicable building codes.
- 2. Contractor shall submit a developed and complete scope of work document, including project specific shop drawings and product data sheets.
- Permits: Contractor shall secure any required permits prior to proceeding with any work and shall coordinate building inspections with the Owner, including the WSU Fire Inspector.

### General Note:

Drawing provided are approximate scale based on original design drawings. Contractor to verify all dimensions.

	11		/DATE	
DRAWN	I INT	11/1	1/2024	
APPRC	VED	11/1	1/2024	
REVISE		12 /	50% CD	
REVISE	.D 2	127	90% CD	
APPRC	VED	2/	′5/2025	
REVISE	D 3			
APPRC	ED FOR	BIDS		
ISSUED F	OR BID	2/	′20/2025	
AYNE STATE UNIVERSITY	TUDENT CENTER	VSU PROJECT #034-350347	ITE PLAN	
Building Science Soluzo-4500Heim Street - Plymouth - Michigan - 481 70. Tel 248				

SP-1

![](_page_20_Figure_0.jpeg)

![](_page_20_Figure_1.jpeg)

![](_page_21_Figure_0.jpeg)

General: The following notes are intended to illustrate general locations of typical work items included in the base bid, and are not intended to be a complete scope of work. Refer to the project specifications for complete description of all work to be performed.

(1.) Remove all existing joint sealant and back-up material from all windows within the exterior plaster wall cladding and provide new back-up material and joint sealant [Approx. 2,700 LF] Refer to Details D2/A-500 and D6/A-500.

 $\langle 2. \rangle$  Remove all existing joint sealant and back-up material from building control joints within the exterior plaster wall cladding and provide new back-up material and joint sealant [Approx. 4,000 LF]. Refer to Detail D1/A-500.

(3.) Apply new pigmented elastomeric coating to exterior plaster walls once crack repairs have been completed [Approx. 31,069 SF].

 $\langle \widehat{4.} \rangle$  Provide wet glazing seals to all glazing perimeters and frame joints. [Approx. 3,420 LF] Refer to Details D3/A-500, D4-A500, and D5-A500.

 $\overline{(5.)}$  Remove and replace existing metal fascia with new, in like kind. [Approx. 400 LF] Refer to Detail D8/A-501.

6. Replace curtain wall snap covers, where missing. Provide unit price for this work.

7. Route and seal cracks in the existing plaster wall prior to new elastomeric coating. Paint to match existing color conditions. [Approx. 24 LF]. Refer to Detail D7/A501.

General Note:

Drawing provided are approximate scale based on original design drawings. Contractor to verify all dimensions.

DRAWN APPROV REVISED APPROV REVISED	INI INT VED D 1 VED D 2	TIALS/ 11/11 11/11 ! 12/1	/DATE 1/2024 1/2024 50% CD 9/2024 90% CD
APPRON REVISED APPRON APPROVE ISSUED FO	/ED ) 3 /ED D FOR E R BID	2/ IIDS 2/2	5/2025
WAYNE STATE UNIVERSITY	STUDENT CENTER	WSU PROJECT #034-350347	SOUTH ELEVATION
	<b>(b</b> ) Building Science Solutions	Building and Construction	200-45000 Helm Street · Plymouth · Michigan · 48170 · Tel 248 957.9911
		WAYNE STATE	

![](_page_22_Figure_0.jpeg)

![](_page_22_Figure_1.jpeg)

(120)	(19)	<18∋195'-0"	17>	15.5 (15)		TYP. APPLY COATING TO PLASTER WALLS
						(APPROX. 8,760 SF)
	MEST ELEVATI	<b>ON - NORTH</b>				
					ROOF OVERFLOW	

# WEST ELEVATION - SOUTH END SCALE: N.T.S.

![](_page_22_Figure_4.jpeg)

to verify all dimensions.

![](_page_23_Figure_0.jpeg)

06

NORTH ELEVATION SCALE: N.T.S.

General: The following notes are intended to illustrate general locations of typical work items included in the base bid, and are not intended to be a complete scope of work. Refer to the project specifications for complete description of all work to be performed.

- (1.) Remove all existing joint sealant and back-up material from all windows within the exterior plaster wall cladding and provide new back-up material and joint sealant [Approx. 2,700 LF] Refer to Details D2/A-500 and D6/A-500.
- (2.) Remove all existing joint sealant and back-up material from building control joints within the exterior plaster wall cladding and provide new back-up material and joint sealant [Approx. 4,000 LF]. Refer to Detail D1/A-500.
- (3.) Apply new pigmented elastomeric coating to exterior plaster walls once crack repairs have been completed [Approx. 31,069 SF].
- $\langle 4. \rangle$  Provide wet glazing seals to all glazing perimeters and frame joints. [Approx. 3,420 LF] Refer to Details D3/A-500, D4-A500, and D5-A500.
- (5.) Remove and replace existing metal fascia with new, in like kind. [Approx. 400 LF] Refer to Detail D8/A-501.
- (6.) Replace curtain wall snap covers, where missing. Provide unit price for this work.
- $\overline{(7.)}$  Route and seal cracks in the existing plaster wall prior to new elastomeric coating. Paint to match existing color conditions. [Approx. 24 LF]. Refer to Detail D7/A501.

Level 4 134' - 8"

<u>Roof</u> 185' - 8"

2012104-FP07 170' - 8"

Level 3 122' - 8"

Level 2 112' - 0"

- CLEAN AND PAINT Plaster Soffit

<u>Level 1</u> 100' - 0"

# INITIALS/DATE DRAWN INT 11/11/2024 APPROVED 11/11/2024 50% CD REVISED 1 APPROVED 12/19/2024 REVISED 2 90% CD APPROVED 2/5/2025 REVISED 3 APPROVED APPROVED FOR BIDS ISSUED FOR BID 2/20/2025 Ņ C C C **JSITY** #O3 STATE UNIVE ENT CENTER NORTH ELEVATION

WAYNE & STUDEN WSU F

Building Science Solutions Building and Construction reet - Plymouth - Michigan - 481 70 · Tel 248 957.9911

<mark>.</mark>S

WAYNES

A-103

General Note:

Drawing provided are approximate scale based on original design drawings. Contractor to verify all dimensions.

![](_page_24_Figure_0.jpeg)

![](_page_25_Figure_0.jpeg)

![](_page_25_Figure_1.jpeg)

![](_page_25_Picture_2.jpeg)

INITIALS/
DRAWN 90
APPROVED 2/5/2
REVISED 1
APPROVED
REVISED 2
APPROVED
REVISED 3
REVISED 3
APPROVED
APPROVED FOR BIDS
ISSUED FOR BID 2/20
37
O O
ကို
╡╝╝╗┊
St ct 2
tio
ut
Sol Str
) e ; e ;
CC
l cie
J S S
ild
Bu Bu
/
<b>A-50</b>
INITIALS/ DRAWN 90 APPROVED 2/5/3 REVISED 1 APPROVED 2 APPROVED 7 APPROVED 7 APPROVED 1 APPROVED 507 BIDS ISSUED FOR BID 2/20 APPROVED 12/20 APPROVED 12/20

# WAYNE STATE UNIVERSITY BIOLOGICAL SCIENCES BUILDING - ENCLOSURE REPAIRS WSU PROJECT # 089-353764

![](_page_26_Figure_1.jpeg)

Location Map

Scale: N.T.S.

-SITE LOCATION

![](_page_26_Picture_5.jpeg)

	ן  דואו	NITIALS/DATE
APPRC		11/1/2024
50% C	D	1/13/2025
APPRC 90% C	VED	1/13/2025 2/5/2025
APPRC	VED	
REVISE	D 3	
APPRC	ED FOR	BIDS
<b>NIVERSITY</b>	INCES BUILDING	ст #089-353764
WAYNE STATE UN	BIOLOGICAL SCIEN	WSU PROJEC
	Ruilding Science Solutions	200-45000 Helm Street · Plymouth · Michigan · 48170 · Tel 248.957.9911
		VANNE STATE

COVER

# BUILDING LOCATION

![](_page_27_Picture_0.jpeg)

# STAGING/DUMPSTER AREA. COORDINATE WITH WSU PROJECT MANAGER FOR TRAFFIC AND EXACT LOCATION

# - ENTRY/EXIT POINT AT WARREN AVE

GENERAL NOTES:

- 1. Drawings and specifications are intended to be a schematic representation of the existing conditions and overall design intent. Contractor is responsible to review existing conditions and develop the specific scope of work for the project, which shall meet the design intent as well as be in accordance with all applicable building codes.
- Contractor shall submit a developed and complete scope of work document, including project specific shop drawings and product data sheets.
- Permits: Contractor shall secure any required permits prior to proceeding with any work and shall coordinate building inspections with the Owner, including the WSU Fire Inspector.

DRAWN INT 11/1/2024 APPROVED 11/13/2025 APPROVED 2/5/2025 APPROVED 3 APPROVED TOR BIDS ISSUED FOR BID 2/20/2025 BIOLOGICAL SCIENCES BUILDING SSUED FOR BID 2/20/2025 APPROVED SOLUCION NSUE DOUGLOUS 1000 APPROVED 10000 APP
APPROVED 11/1/2025 APPROVED 2/5/2025 APPROVED 3 APPROVED BIJS ISSUED FOR BID 2/20/2025 SSUED FOR BID 2/20/2025 APPROVED FOR BID 2/20/2025 BIOLOGICAL SCIENCES BUILDING APPROVED BIJS SSUED FOR BID COUST. CIENCES BUILDING APPROVED 1000000000000000000000000000000000000
50% CD 1/13/2025 APPROVED 1/13/2025 APPROVED 2/5/2025 APPROVED 3 APPROVED FOR BIDS ISSUED FOR BID 2/20/2025 BIOLOGICAL SCIENCES BUILDING BIOLOGICAL S
APPROVED 1/13/2025 90% CD 2/5/2025 APPROVED 3 APPROVED 3 APPROVED FOR BIDS ISSUED FOR BID 2/20/2025 BIOLOGICAL SCIENCES BUILDING BIOLOGICAL SCIENCES BUILDING APPROVED 101 2020 BIOLOGICAL SCIENCES BUILDING ARVNE SCIENCE SOULDING BIOLOGICAL SCIENCES BUILDING BIOLOGICAL SCIENCES BUILDING BIOLOGICAL SCIENCES BUILDING BIOLOGICAL SCIENCES BUILDING ARVNE SUBJ 2/20/2025 BIOLOGICAL SCIENCES BUILDING BIOLOGICAL SCIENCES BUILDING APPROVED 101 2020 APPROVED
APPROVED REVISED 3 APPROVED FOR BIDS ISUED FOR BID BIOLOGICAL SCIENCES BUILDING BIOLOGICAL SCIENCES BUILDING BIOLOGICAL SCIENCES BUILDING BUILDING BUILDING BUILDING BUILDING BUILDING APPROVED 101 248-957.901 SIE PLAN SIE PLAN BUILDING BUILD
RE VISED 3 APPROVED APPROVED FOR BIDS ISSUED FOR BID BIOLOGICAL SCIENCES BUILDING BIOLOGICAL SCIENCES BUILDING BIOLOGICAL SCIENCES BUILDING BIOLOGICAL SCIENCES BUILDING BIOLOGICAL SCIENCES BUILDING NSU PROJECT #089–353764 SIE PLAN SIE PLAN
APPROVED FOR BIDS SSUED FOR BID Building Science Solutions Building and Construction Building and Building and Buildin
Tester: Pymouth: Midligan donstruction       STE PLAN         2004500Hem Steet: Pymouth: Midligan: 48170: Tel 248957.991       STE PLAN         2004500Hem Steet: Pymouth: Midligan: 48170: Tel 248957.991       STE PLAN         2004500Hem Steet: Pymouth: Midligan: 48170: Tel 248957.991       STE PLAN
2004000 Image: Solutions       Warke State UNIVERSITY         Building Science Solutions       BOLOGICAL SCIENCES BUILDING         Building and Construction       WSU PROJECT #089-353764         Sife PLAN       Sife PLAN
Duilding Science Solutions       Building Science Solutions         Building and Construction       BOLOGICAL SCIENCES BUILDING         Description Street: Plymouth: Michigan: 48170: Tel 248,957,991       BOLOGICAL SCIENCES BUILDING         Description Street: Plymouth: Michigan: 48170: Tel 248,957,991       BIOLOGICAL SCIENCES BUILDING         Description Street: Plymouth: Michigan: 48170: Tel 248,957,991       BIOLOGICAL SCIENCES BUILDING         Description Street: Plymouth: Michigan: 48170: Tel 248,957,991       BIOLOGICAL SCIENCES BUILDING
WA WA Building Science Solutions BIO BIO BIO BIO BIO BIO BIO BIO

![](_page_28_Figure_0.jpeg)

![](_page_28_Figure_1.jpeg)

AD-0177.0

 $\bigcirc$ 

-

AD01727

E

MPAULA PAG

G

SOUTH ELEVATION

General: The following notes are intended to illustrate general locations of typical work items included in the base bid, and are not intended to be a complete scope of work. Refer to the project specifications for complete description of all work to be performed.

- 1. Remove all existing joint sealant and back-up material from all windows and provide new back-up material and joint sealant for all elevations. Refer to Detail D9/A501. [Approx.5,150 LF]
- 2. Provide wet glazing seals to all glazing perimeters and frame joints. Refer to Details D15/502 & D7/A501 & D8/A501. [Approx. 7,020 LF]
- (3.) Remove and replace failed insulated glazing units in like kind. Provide unit price for IGU replacements.
- (4.) Remove all existing expansion joint sealant and back-up material and provide new back-up material and joint sealant. Refer to Detail D3/A500. [Approx. 2,435 LF]
- 5. Remove and replace existing thru-wall flashing at window heads with new. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Details D11/A501 and D12/A502. [Approx. 1,500 LF]
- 6. Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Details D1/A500 & D2/A500.
   [Approx. 445 SF total for all elevations]. Provide a unit price for localized and isolated repairs.
- 7.) Remove and replace spalled brick with new. Refer to Detail D16/A502 [Approx. 24 bricks]
- 8. Repair damaged and/or spalled stone in the limestone bands using Dutchman style repairs. Refer to Details D4/A500, D5/A500 & D6/A500. [Approx. 28 SF]
- 9. If surface corrosion with no section loss is visible, clean and paint existing lintels. If heavy rust pack and section loss is visible in the window lintel, **provide a unit price to remove and replace existing lintels with new** and associated flashing above windows. Refer to Details D11/501 and D12/A502. [Approx. 1,500 LF]
- 10 Investigate bowing in the brick at the expansion joints along the north elevation. Exact anchor and repair method will need to be field determined. For bidding purposes, include 40 labor hours and \$7,500 cost for equipment and material.
- (11) Repair tears to the roof membrane on the northeast corner of the building. Refer to Detail D15/A502 [Approx. 15 SF].
- 12. Remove all existing joint sealant material from the concrete parapets and install new sealant. Refer to Detail D13/A502. [Approx. 1,220 LF]
- 13. Re-secure detached mechanical fixtures above greenhouse roof and fill voids visible on interior wall [Approx. 3 locations]. Additionally, clear debris from valleys in between greenhouse windows/roof. Refer to Detail D14/A502.

![](_page_28_Figure_17.jpeg)

![](_page_28_Figure_18.jpeg)

**NOTE:** THE SYMBOLS SHOWN ARE USED ON OUR DRAWINGS TO INDICATE ENCLOSURE FEATURES. ADDITIONAL SYMBOLS MAY BE SHOWN ON THE DRAWING FOR SPECIFIC PROJECTS.

General Note: Drawing provided are approximate scale based on original design drawings. Contractor to verify all dimensions.

	IN	IITIALS	/date	
DRAWN	INT	11/1	/2024	
APPRO	VED	11/1	/2024	
50% CI	D	1/13	8/2025	
APPRO	VED	1/13	8/2025	
90% CI	D	2/5	/2025	
APPRO	VED			
REVISE	D 3			
APPRO	VED			
APPROVI	ED FOR	BIDS		
ISSUED FO	OR BID	2/2	0/2025	
WAYNE STATE UNIVERSITY	BIOLOGICAL SCIENCES BUILDING	WSU PROJECT #089-353764	NORTH/SOUTH ELEVATIONS	
Building Science Solutions Building and Constructior 2004500Helm Street - Plymouth - Michigan - 48170. Tel 248.957.991				

![](_page_28_Figure_22.jpeg)

![](_page_29_Figure_0.jpeg)

![](_page_29_Figure_1.jpeg)

- complete the work. Refer to Details D11/A501 and D12/A502. [Approx. 1,500 LF]

- \$7,500 cost for equipment and material.

to verify all dimensions.

![](_page_30_Figure_0.jpeg)

- General: The following notes are intended to illustrate general locations of typical work items included in the base bid, and are not intended to be a complete scope of work. Refer to the project specifications for complete description of all work to be performed.
- Remove all existing joint sealant and back-up material from all windows and provide new back-up material and joint sealant for all elevations. Refer to Detail D9/A501. [Approx.5,150 LF]
   Provide wet glazing seals to all glazing perimeters
- Provide wet glazing seals to all glazing perimeters and frame joints. Refer to Details D15/502 & D7/A501 & D8/A501. [Approx. 7,020 LF]
   Remove and replace failed insulated glazing units in
- Remove all existing expansion joint sealant and back-up material and provide new back-up material and joint sealant. Refer to Detail D3/A500. [Approx. 2,435 LF]
- 2,435 LF]
  S. Remove and replace existing thru-wall flashing at window heads with new. Removal and replacement of min. three (3) courses of brick will be required to complete the work. Refer to Details D11/A501 and D12/A502. [Approx. 1,500 LF]

		8				
OUTLINE OF COOLING TOWERS EXHAUST STACKS (BEYOND)		+2	23'-4"	AUST STACKS		
	KE PANEL		3			FBROUNDLE PARE COPEQNATE W/M
			0			
					₽	
		(P.				
	(04) (A-102)	WEST ELEVA	ΓΙΟΝ			

- Remove and replace failed insulated glazing units in like kind. Provide unit price for IGU replacements.
- 6. Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Details D1/A500 & D2/A500.
   [Approx. 445 SF total for all elevations]. Provide a unit price for localized and isolated repairs.
- Remove and replace spalled brick with new. Refer to Detail D16/A502 [Approx. 24 bricks]
- 8. Repair damaged and/or spalled stone in the limestone bands using Dutchman style repairs. Refer to Details D4/A500, D5/A500 & D6/A500. [Approx. 28 SF]
- 9. If surface corrosion with no section loss is visible, clean and paint existing lintels. If heavy rust pack and section loss is visible in the window lintel, **provide a unit price to remove and replace existing lintels with new** and associated flashing above windows. Refer to Details D11/501 and D12/A502. [Approx. 1,500 LF]
- 10 Investigate bowing in the brick at the expansion joints along the north elevation. Exact anchor and repair method will need to be field determined. For bidding purposes, include 40 labor hours and \$7,500 cost for equipment and material.

- (11) Repair tears to the roof membrane on the northeast corner of the building. Refer to Detail D15/A502 [Approx. 15 SF].
- 12. Remove all existing joint sealant material from the concrete parapets and install new sealant. Refer to Detail D13/A502. [Approx. 1,220 LF]
- 13. Re-secure detached mechanical fixtures above greenhouse roof and fill voids visible on interior wall [Approx. 3 locations]. Additionally, clear debris from valleys in between greenhouse windows/roof. Refer to Detail D14/A502.

![](_page_30_Figure_16.jpeg)

![](_page_31_Figure_0.jpeg)

NEW BACKER ROD	INITIALS/DATE DRAWN INT 1/10/2025 APPROVED 11/1/2024 50% CD 1/13/2025 APPROVED 1/13/2025 90% CD 2/5/2025 APPROVED Z REVISED 3 APPROVED FOR BIDS ISSUED FOR BID 2/20/2025
EXPANSION JOINT DETAIL	MAYNE STATE UNIVE BIOLOGICAL SCIENC S WSU PROJECT DETAILS
SETTING MORTAR HMAN < 3/4" WE SCREW HMENT AND H SURFACE PROVIDE STONE DUTCHMAN TO MATCH EXISTING ADJACENT STONE COLOR PDOFILE & TEXTURE OLOR	Building Science Solutions Building and Construction 2004500Helm Street - Plymouth - Michigan - 481 70 - Tel 248 957, 991
AN > 3/4" THICK, "IDE X 1/16" S.S. X 4" LONG S.S. O CONNECTION. VRY W/ 1/8" S.S. ADHESIVE. TOP JUTCHMAN SIM. N IS 6" X 6" USE DIA. DROP PINS	
TYPICAL LIMESTONE DUTCHMAN REPAIR	A-500

![](_page_32_Figure_0.jpeg)

![](_page_32_Picture_1.jpeg)

![](_page_32_Picture_2.jpeg)

![](_page_33_Picture_0.jpeg)

![](_page_33_Picture_1.jpeg)

# TYPICAL THROUGH WALL FLASHING/LINTEL REPLACEMENT DETAIL - LIMESTONE

RE-SECURE DETACHED MECHANICAL FIXTURES

![](_page_33_Picture_4.jpeg)

![](_page_33_Picture_5.jpeg)

FILL VOID AT – MECHANICAL FIXTURES

![](_page_33_Picture_8.jpeg)

**GREENHOUSE REPAIRS - EAST ELEVATION** 

![](_page_33_Picture_10.jpeg)

![](_page_33_Picture_12.jpeg)

EXISTING BRICK MASONRY. BRICK COURSES MAY REQUIRE REMOVAL FOR THROUGH-WALL FLASHING WORK. REMOVE AND REPLACE BRICK WHERE REQUIRED (APPROX. THEE (3) COURSES).

PROVIDE TERMINATION BAR AND SEAL WITH MASTIC. SEAL ALL FASTENER PENETRATIONS.

EXISTING FELT UNDERLAYMENT TO BE LAPPED OVER TERMINATION BAR

PROVIDE SELF-ADHERED FLASHING. INSTALL PER MANUFACTURER'S INSTALLATION INSTRUCTIONS. SEAL ALL BOLT PENETRATION WITH COMPATIBLE SEALANT.

REMOVE AND SALVAGE EXISTING LIMESTONE PANEL.

IF PITTING IS PRESENT IN THE STEEL LINTEL, REMOVE EXISTING STEEL LINTEL AND PROVIDE NEW 3.5" X 3.5" X 3/8" \_ STEEL LINTEL FASTENED TO EXISTING STRUCTURE VIA 5/8" STAINLESS STEEL HEX BOLTS SPACED 42" O.C. MAX. PRIME AND PAINT. CLEAN, PRIME, AND PAINT IF ONLY SURFACE CORROSION IS PRESENT.

PROVIDE CELL VENT WEEPS EVERY HEAD JOINT

PROVIDE STAINLESS STEEL HEMMED DRIP EDGE OVER NEW LINTEL WITH 3" LAPS FULLY SEALED WITH BUTYL. SET FLASHING IN BED OF SEALANT. PROVIDE PREFABRICATED INSIDE/OUTSIDE CORNERS AND END DAMS, AS REQUIRED.

EXISTING WINDOW TO REMAIN

WHERE TEARS IN THE MEMBRANE -ARE PRESENT, APPLY ROOF PATCHES OF SIMILAR MATERIAL. ROUND THE CORNERS OF THE PATCHES UTILIZING COLD ADHESIVE TO ATTACH. SEAL THE PATCHES WITH SEALANT.

ROOF MEMBRANE REPAIRS

![](_page_33_Picture_25.jpeg)

**PARAPET WALL - CURRENT CONDITION** 

![](_page_33_Picture_27.jpeg)

A-502

INITIALS/DATE

11/1/2024

1/13/2025

1/13/2025

2/5/2025

C

Щ

**P** 

NSM

Science Solution and Construction

Building Suilding

BRICK REPLACEMENT DETAIL

# WSU PROJECT # 167-409636

![](_page_34_Figure_1.jpeg)

![](_page_34_Picture_3.jpeg)

![](_page_35_Picture_0.jpeg)

![](_page_35_Picture_1.jpeg)

PROPOSED STAGING / DUMPSTER AREA. FINAL LOCATION TO BE DETERMINED WITH WSU PROJECT MANAGER

![](_page_35_Picture_3.jpeg)

SITE PLAN

NOT TO SCALE

ENTRY/EXIT POINT AT WARREN AVENUE	INITIALS/DATE DRAWN 11/1/2024 APPROVED 11/1/2024 REVISED 1 50% CD APPROVED 1/21/2025 REVISED 2 90% CD APPROVED 2/5/2025 REVISED 3 APPROVED SIDS ISSUED FOR BIDS ISSUED FOR BID 2/20/2025
	WAYNE STATE UNIVERSITY ENGINEERING TECHNOLOGY BUILDING WSU PROJECT #167-409636 SITE PLAN
	Building Science Solutions Building and Construction 200-4500 Helm Street - Plymouth - Michigan - 481 70 - Tel 248,957,9911
TES: nd specifications are intended to be a schematic tion of the existing conditions and overall design tractor is responsible to review existing and develop the specific scope of work for the	
ich shall meet the design intent as well as be in with all applicable building codes. shall submit a developed and complete scope of ment, including project specific shop drawings ct data sheets. ontractor shall secure any required permits prior ling with any work and shall coordinate building s with the Owner, including the WSU Fire	SP-1

GENERAL NOTES:

- Drawings and specifications are intended to be a schemat representation of the existing conditions and overall desig intent. Contractor is responsible to review existing conditions and develop the specific scope of work for the project, which shall meet the design intent as well as be in accordance with all applicable building codes.
- Contractor shall submit a developed and complete scope work document, including project specific shop drawing and product data sheets.
- Permits: Contractor shall secure any required permits pric to proceeding with any work and shall coordinate buildin inspections with the Owner, including the WSU Fire Inspector.

![](_page_36_Figure_0.jpeg)

EAST ELEVATION SCALE: N.T.S.

02

Drawing provided are approximate scale based on original design drawings. Contractor to verify all dimensions.

![](_page_37_Figure_0.jpeg)

![](_page_37_Figure_1.jpeg)

Q.

![](_page_38_Figure_0.jpeg)

## NOTE: COLOR "A" AND "B" TO BE DETERMINED BY WSU PROJECT MANAGER

General Note:

Drawing provided are approximate scale based on original design drawings. Contractor to verify all dimensions.

# ISSUED FOR BID 2/20/2025 BUILDING 409636 409 TECHNOLOGY WAYNE STATE UNIVERSITY #167 СШ СШ EDULE ERING Ô SC Ľ NSM PAINT ENGIN Building Science Solutions Building and Construction Street · Plymouth · Michigan · 481 70 · Tel 248 957.9911 <mark>.</mark>S WAYNEST

A-102

INITIALS/DATE

DRAWN

APPROVED

REVISED 1

APPROVED

REVISED 2

APPROVED

REVISED 3

APPROVED

APPROVED FOR BIDS

90% CD

2/5/2025

![](_page_39_Figure_0.jpeg)

![](_page_39_Figure_3.jpeg)

![](_page_40_Figure_0.jpeg)

TYPICAL CONCRETE SPALL REPAIR DETAIL

### TYPICAL FULL DEPTH CONCRETE REPAIR DETAIL

A-501

DIZ

![](_page_41_Figure_0.jpeg)

![](_page_42_Figure_0.jpeg)

![](_page_43_Figure_0.jpeg)

**BUILDING SIGNAGE ATTACHMENT** 

![](_page_43_Figure_3.jpeg)

![](_page_43_Picture_4.jpeg)

# PAULINE KNAPP BUILDING - ENCLOSURE REPAIRS WSU PROJECT #509-404249

![](_page_44_Figure_1.jpeg)

![](_page_44_Picture_2.jpeg)

![](_page_44_Picture_3.jpeg)

![](_page_45_Picture_0.jpeg)

# STAGING/DUMPSTER AREA. COORDINATE WITH WSU PROJECT MANAGER FOR TRAFFIC AND EXACT LOCATION

SITE PLAN

NOT TO SCALE

![](_page_45_Picture_4.jpeg)

# ENTRY/EXIT POINT AT JOHN R. ST.

GENERAL NOTES:

- Drawings and specifications are intended to be a schematic representation of the existing conditions and overall design intent. Contractor is responsible to review existing conditions and develop the specific scope of work for the project, which shall meet the design intent as well as be in accordance with all applicable building codes.
- Contractor shall submit a developed and complete scope of work document, including project specific shop drawings and product data sheets.
- Permits: Contractor shall secure any required permits prior to proceeding with any work and shall coordinate building inspections with the Owner, including the WSU Fire Inspector.

COVER

![](_page_46_Figure_0.jpeg)

![](_page_47_Figure_0.jpeg)

![](_page_48_Figure_0.jpeg)

![](_page_48_Picture_5.jpeg)

General: The following notes are intended to illustrate general locations of typical work items included in the base bid, and are not intended to be a complete scope of work. Refer to the project specifications for complete description of all work to be performed.

- (1.) Remove all existing joint sealant and back-up material from all windows and provide new back-up material and joint sealant. Refer to Detail D2/A500 [Approx.1,700 LF]
- 2. Provide wet glazing seals to all glazing perimeters and frame joints. Refer to Details D3/A500 & D4/A500. [Approx. 4,700 LF]
- $\widehat{(3.)}$  Remove and replace, with new, thru-wall flashing above the front entrance canopy. Refer to Detail D16/A502. [Approx. 30 LF]
- $\overline{\langle 4. \rangle}$  Remove all existing control joint sealant and back-up material and provide new back-up material and control joint sealant. Refer to Detail D1/A500. [Approx. 270 LF]
- (5.) Cut and tuckpoint damaged and deteriorated mortar joints. Refer to Details D5/A500 & D6/A500. [Approx. 503 SF total for all elevations]
- $\widehat{(6.)}$  Rout and seal cracks in the brick wall. Refer to Details D8/A501. [Approx. 6 LF]
- $\overline{(7.)}$  Replace damaged and/or spalled brick. Refer to Detail D7/A501 [Approx. 14 bricks]
- (8.) Apply clear seal to all locations with brick veneer on all elevations. [Approx. 6,560 SF]
- $\widehat{(9.)}$  Reflash the perimeter of the roof parapet wall (Area A), which involves a stripping repair utilizing either a similar roof cement and reinforcement mesh (with an aluminum coating finish) or a heavier ply sheet. Refer to Detail D16/A502.
- (10.) Reflash the perimeter of the roof parapet wall (Area B), which involves a stripping repair utilizing either a similar roof cement and reinforcement mesh (with an aluminum coating finish) or a heavier ply sheet. Refer to Detail D16/A502.
- (11.) Repair isolated areas of membrane tears on both roof areas A & B. Repairs include cleaning the area, applying roof cement and patch to the repair location and sealing the perimeter edges of the patch with sealant. Refer to Detail D15/A502.
- (12) Where Area A lower porcelain panels are bowing, the panels are to be removed, re-secured, and new sealant applied. Panels are to be stored in a secure location. New anchors may need to be engineered and fabricated. Contractor to provide means and methods for this repair. Refer to Details D13/A502. [Approx. 422 LF]. Provide time and expense rate for this work.
- (13.) Repair concrete beams where porcelain enamel panels are moved. Extent of damage to the concrete beams is unknown; however, work will likely include removing any loose or cracked concrete, cleaning and coating any exposed rebar with a rust primer, patching the damaged areas, and applying a liquid AVB coating. Provide a unit price for this work. Refer to Details D9/A501, D10/A5012, D11/A501 & D12/A501.

### SYMBOL LEGEND

![](_page_48_Picture_21.jpeg)

Drawing provided are approximate scale based on original design drawings. Contractor to verify all dimensions.

![](_page_48_Picture_23.jpeg)

N  $\mathbf{O}$ UNIVERSITY  $( \mathbf{7} )$ ELEVATION B STATE KNAPI SOUTH WAYNE SU PAUL 3

Ο

Science Solutions and Construction Building Building S

![](_page_48_Picture_26.jpeg)

![](_page_49_Figure_0.jpeg)

![](_page_49_Figure_1.jpeg)

![](_page_49_Figure_4.jpeg)

applying roof cement and patch to the repair location and sealing the perimeter edges of the patch with sealant. Refer to Detail D15/A502.

Drawing provided are approximate scale based on original design drawings. Contractor to verify all dimensions.

![](_page_50_Figure_0.jpeg)

WET SEAL LOCATIONS

![](_page_50_Picture_4.jpeg)

![](_page_51_Figure_0.jpeg)

- FIELD.
- AND REPLACED TO A DEPTH OF 3" MAXIMUM. DO NOT OVERCUT OR DAMAGE EDGES OF ADJACENT MASONRY.
- (03) CLEAN AND REPOINT THE EXISTING EXPOSED BACK-UP WALL WHERE EXTENTS OF LOCALIZED BRICK REBUILD EXCEEDS 2SF. INSTALL NEW STAINLESS STEEL WALL TIES AT A MIN. OF 1 PER 1.5 SF. NOTIFY ENGINEER WHERE CRACKING APPEARS TO EXTEND THROUGH BACK-UP MASONRY. DO NOT REPLACE HEADER BRICKS IF NOT CRACKED.
- INSTALLED WITH TYPE N MORTAR. NEW BRICK MUST BE REVIEWED AND APPROVED BY THE OWNER/ARCHITECT. REPLACEMENT BRICKS SHALL MATCH THE SIZE, SHAPE, TEXTURE AND COLOR OF THE EXISTING BRICK. PLACE THE NEW BRICK TO MATCH THE ADJACENT SURROUNDING COURSING.
- (05) RAKE THE MORTAR JOINTS ON ALL FOUR SIDES OF THE NEWLY INSTALLED MORTAR TO CURE FOR 24 HOURS PRIOR TO POINTING THE JOINTS WITH THE APPROVED MORTAR FOLLOWING THE REQUIREMENTS OF THE TYPICAL MASONRY REPOINTING DETAIL

![](_page_51_Figure_8.jpeg)

![](_page_51_Picture_9.jpeg)

TYPICAL VERTICAL PARTIAL DEPTH CONCRETE REPAIR

SYS

WO COATS OF APPROVED EPOXY COATING STEM TO EXPOSED REBAR AND CONCRETE EMBEDDED REBAR OR LIFT ANCHOR. CHIP MOVE DETERIORATED CONCRETE (LOOSE, CKED, DELAMINATED, SPALLED) TO SOUND E. PROVIDE 3/4" MIN. CLEARANCE AROUND RCING BARS WHERE MORE THAN HALF THE PERIMETER OF THE BAR IS EXPOSED	INITIALS/DATE DRAWN INT 11/1/2024 APPROVED 11/1/2024 REVISED 1 50% CD APPROVED 1/21/2025 REVISED 2 90% CD APPROVED 2/5/2025 REVISED 3 2/5/2025 APPROVED 50 BID 2/20/2025
AROUND DELAMINATION. OUTLINE EXACT IETE REPAIRS IN THE FIELD MARKING WITH SRETE SURFACE. CONTRACTOR TO SOUND OR REPAIR AREA TO CONFIRM EXTENT OF L AND TO ENSURE COMPLETE DEMOLITION TO SOUND SUBSTRATE W LIQUID AVB OVER REPAIRED CONCRETE W LIQUID AVB OVER REPAIRED CONCRETE TYPICAL CONCRETE SPALL REPAIR	VAYNE STATE UNIVERSITY PAULINE KNAPP BUILDING NSU PROJECT #509-404249 DETAILS
GENERAL NOTES:         1.) SOUND CONCRETE ALL AROUND DELAMINATION. OUTLINE EXACT LOCATION OF CONCRETE REPAIRS IN THE FIELD MARKING WITH PAINT ON CONCRETE SURFACE. CONTRACTOR TO SOUND PERIMETER OR REPAIR AREA TO CONFIRM EXTENT OF DELAMINATION OR SPALL AND TO ENSURE COMPLETE DEMOLITION TO SOUND SUBSTRATE         2.) CHIP AND REMOVE DETERIORATED CONCRETE (LOOSE, CRACKED, DELAMINATED, SPALLED) TO SOUND CONCRETE. PROVIDE 3/4" MIN. CLEARANCE AROUND REINFORCING BARS WHERE MORE THAN HALF THE PERIMETER OF THE BAR IS EXPOSED         3.) SANDBLAST EXISTING CONCRETE AND REINFORCEMENT TO PROVIDE CLEAN SURFACE FREE OF DUST, DEBRIS, BIOLOGICAL GROWTH, OILS OR COATINGS. IN AREAS WHERE THE EXISTING STEEL MEMBERS (REBAR, STRUCTURAL STEEL) HAVE RUSTED AND LOST EXCESS OF 10% OF THEIR CROSS SECTION, AREA SHALL BE BROUGHT TO ENGINEERS ATTENTION. CORRODED REINFORCEMENT SHALL BE	P Scottence Solutions Building Science Solutions Building and Construction 200-4500 Helm Street - Plymouth - Michigan - 481 70 - Tel 248 957.9911
<ul> <li>A THEINTON, CORRODED AND REINFORCEMENT SHALL BE REMOVED AND REPLACED AT ENGINEERS DISCRETION. REPLACEMENT REBAR SHOULD BE #4 EPOXY COATED REBAR DEVELOPED MIN. 6" INLINE WITH EXISTING REINFORCEMENT.</li> <li>4.) CUT BACK ANY EXPOSED REBAR IN PATCH AREA SUCH THAT A MIN. CONCRETE COVER OF 1" CAN BE ACHIEVED WITHIN CONCRETE PATCH AREA</li> <li>5.) DESIGN AND CONSTRUCT FORMWORK AS NECESSARY TO BE READILY REMOVABLE WITHOUT IMPACT, SHOCK, OR DAMAGE TO NEW CONCRETE SURFACES AND ADJACENT MATERIALS.</li> <li>6.) PLACE, FINISH, AND CURE CONCRETE PATCH MATERIAL IN ACCORDANCE WITH MANUFACTURER SPECIFICATIONS. FINISH PATCH TO MATCH EXISTING/ADJACENT CONCRETE SURFACE PROFILE AND TEXTURE.</li> <li>7.) SAWCUT ALL EDGES OF REPAIRS USING A TILTED BLADE TO PROVIDE A KEYED PATCH. MIN. SAWCUT 1/2" DEPTH.</li> </ul>	

 $A - 50^{\circ}$ 

![](_page_52_Figure_0.jpeg)